

PRODUCT CHANGE NOTIFICATION COVERSHEET

Models 532, 533, 580, 581, 578,

CTS Part Number: 579, 585, 586, 575, 576, VFTX301, VFTX302, VFTX332

Product Description: Temperature Compensated Crystal Oscillator [TCXO]

Customer: Various **Customer Part Number:** Various

Change Notification Only - No Customer Response Required

Customer Authorization Required - Please Confirm Acceptance by E-Mail

Reason for PCN: Obsolescence of +5.0V Option for TCXO models 532, 533, 580, 581, 578, 579, 585,

586, 575, 576, VFTX301, VFTX302 and VFTX332.

Description for Change: CTS is announcing obsolescence of the +5.0V option for TCXO models 532, 533,

580, 581, 578, 579, 585, 586, 575, 576, VFTX301, VFTX302 and VFTX332.

As TCXO IC supplier Asahi Kasei Microdevices [AKM] recovers from a factory fire in Q4 2020, they have announced they are no longer supporting chipsets that operate

at +5.0V.

 ${\sf IC}$ supply is very limited and CTS cannot guarantee availability, therefore last time

buy opportunities will not be offered.

[See following page for list of part numbers that had activity in CTS system.]

Change Instructions: Models 532, 533, 580, 581, 578, 579, 585, 586, 575, 576, VFTX301, VFTX302 and

VFTX332 will be EOL without direct replacement. CTS recommends that customers

move to a design that operates at +3.3V or less.

Customer designs that use a 7.0mmx5.0mm [7050] package should also consider

changing to a smaller size, as the larger package is less popular and manufacturing $% \left(1\right) =\left(1\right) \left(1$

capacities are being directed to smaller sizes.

Please contact CTS for support throughout EOL process and for alternate product

recommendations.

Implementation Date: 9/10/2021

Notes: Distribution of this PCN will be managed by CTS Customer Service; through all

customer portals currently on file with CTS, all CTS Distributors and contract

manufacturers [CMs].

CTS Contact: John Metzler

E-Mail: <u>John.Metzler</u>@ctscorp.com

Phone: 630-588-8828

CTS Approvals: CTS internal PCN w/ electronic signatures.



PLATFORMS AND PART NUMBERS AFFECTED

CTS Part Number	CTS Part Number	CTS Part Number	CTS Part Number
532S	578S	575S	VFTX301-xxDxx-
532S25DA13M0000		575S05HT10M0000	
532S25DT20M0000	579S	575S10CC20M0000	VFTX302-xxDxx-
53210002	579S160ITT	575S10CT10M0000	VFTX302-GGDT-20.00MHz [OIO8306]
53210075		575S10DC12M8000	VFTX302-GGDT-25.00MHz [OIO7952]
	585S	575S10HT19M9980	VFTX302-JGDAN-19.2MHz [OIO8633]
580S		575S10HT20M0000	VFTX302-KFDTN-10.000MHz [OIO8626]
580S10005ITT	586S	575S10IT10M0000	VFTX302-KGDTN-10.00MHz [OIO7759]
580S10005HAT	586S25005CT	575S15IA19M2000	VFTX302-LDDTN-12.800MHz [OIO8946]
580S10005ITT	586S25005CTT	575S20CC10M0000	
580S100X2HAT		575S20DC10M0000	VFTX332-xDxx-
	588S	575S25CT10M0000	VFTX332-GDTC-10.000MHz [OIO8771]
581S		575S50HT27M0000	VFTX332-GDTC-20.000MHz [OIO8742]
58110041	589S		
	589S100X2IAT	576S	
		57610027	