

PCN-147200

# **Product Change Notice**

Issue Date: 20-January-2021

### **Change Description:**


Carrier tape pocket design change

# Parts Affected:

AEMD-LB3L-UVB02	AEMD-LB3L-UVC02	AEMD-LB3L-UW002	AEMD-LG3K-XY002	AEMD-LG3K-XZ002
AEMD-LL3K-XYK02	AEMD-LL3K-XYL02	AEMD-LL3K-XZ002	AEMD-LM3L-35002	AEMD-LM3L-45B02
AEMD-LM3L-45C02	AEMD-LY3N-12002	AEMD-LY3N-12J02	AEMD-LY5N-23002	QEMZ-LL3K-XZK02
QEMD-LB7L-UVB02	QEMD-LG7K-XY002	QEMD-LL7K-XYK02	QEMD-LM7L-45B02	QEMD-LY7N-12J02
QEMD-LG6K-XY002	QEMD-LM6L-45B02			

## **Description and Extent of Change:**

The carrier tape design will be modified for better LED fitting. The table below shows the comparison of the existing and new carrier tape design.





#### **Reasons for Change:**

Improvement on the design of the carrier tape, which will allow a firmer positioning of unit inside the pocket.

#### Effect of Change on Fit, Form, Function, Quality, or Reliability:

The change is limited to the carrier tape design only. There is no change in the material of the carrier tape. There is no change in the fit, form and function of the device.

#### **Effective Date of Change:**

Broadcom will start shipping the improved carrier tape 30 days from the notification date. Shipments will contain both existing and new carrier tape design until the inventories of the existing carrier tape are fully depleted.

**Qualification Data:** 

Not applicable

#### Software / Firmware Update:

Not applicable

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.