

PCN: PCN-CCX-42615-007-1

# **Notification Only - Product Change Notice**

Issue Date: September 8, 2016

**Update**:

UPDATED PCN-CCX-42601-003-0 Change to Ordering Part Numbers

**Change Type:** 

Change to Ordering Part Numbers

# Parts Affected:

Current Part Number	New Ordering Part Number	Notes
		BCM53124SKMMLG
BCM53124SKMMLG – B0 version	BCM53124B0SKMMLG	can be used to order CO version

## **Description and Extent of Change:**

This is an update to PCN PCN-CCX-42601-003-0 that was issued on August 19, 2016. This update is specifically for the part-number mentioned in the above table that according to our records you have ordered previously. We have also added a Notes column to the PCN table that reflects the new interpretation of the old part-numbers that we'll still maintain.

Please update the ordering part number per the table above by Sept. 17<sup>th</sup>, 2016.

#### Reasons for Change:

- As part of the acquisition of Broadcom Corp. by Avago Technologies to form a new company, Broadcom Limited, it is necessary to rationalize part numbering to enable smooth ERP integration.
- Broadcom Limited needs to inform you that as of September 17th, 2016, the following Broadcom Limited ordering part numbers will change. All Purchase Orders after that date should reflect the New Ordering Part Number.
- All documentation after that date will reflect the New Ordering Part Number.
- Box labels will gradually transition as inventory with old part number is depleted.
- Part Marking will remain unchanged

# Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no Form/Fit/Function impact.

### **Effective Date of Change:**

Customers are required to order with new part numbers starting – Sept. 17<sup>th</sup>, 2016.

# **Qualification Data:**

No qualification data necessary, as there is no Form/Fit/Function or reliability impacts.

Please contact your Broadcom Limited Sales person or their Customer Account Specialist (CAS) for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.