



Product Change Notification		Date March 17, 2021
Product	IX14/IX10/IX15/IX20/IX20W	
Description of change	New firmware version 21.5.56.106 available for all IX routers. This is a major production release. Digi recommends all customers update their IX products to firmware v21.5.56.106	
Reason for Change	New Firmware Version 21.5.56.106 provides: <ul style="list-style-type: none">• New Features• Enhancements• Bug Fixes• Security Fixes See Release Notes for more details.	
Product Notice	<p>A new stable firmware version has been released for the IX, version 21.5.56.106. Use the link below to view the full list of changes, features, and fixes included in the new firmware.</p> <p>IX Release Notes</p> <p><u>To take advantage of the new features, you must take action to update your device.</u> Refer to the instructions to update your firmware in the release notes above for more information.</p> <p>Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team at tech.support@digi.com.</p>	
Affected Part Numbers	IX14-L301, IX14-M301, IX14-M401, IX14-M601, IX14-M901, IX10-00G4 IX20-00G4, IX20-0AG4, IX20-W0G4, IX20-WAG4, IX15-00G4-XB2, IX15-00G4-XBP2	
Timing of Change	Effective Immediately	