

Date Issued: January 15, 2016

End of Life Notification EQL16.001

This End of Life (EOL) notification concerns 3 variants of Finisar's 10GBASE-SR/SW SFP+ transceivers: FTLX8570D3Bxx, FTLX8571D3Bxx and FTLX8572D3Bxx.

Affected Part Numbers and Recommended Replacement Part Numbers

Finisar's custom and generic part numbers affected by this EOL notice are shown in the following table, along with the recommended replacement part numbers:

Current P/Ns	Suggested Replacement P/Ns	
FTLX8570D3BCLxxx	FTLX8574D3BCLxxx	
FTLX8571D3BCLxxx	FILA65/4D3BCLXXX	
FTLX8572D3BCLxxx	no replacement	
FTLX8570D3BNLxxx	FTLX8574D3BNLxxx	
FTLX8571D3BNLxxx	FILAOD/4D3DINLXXX	
FTLX8571D3BCVxxx	FTLX8574D3BCVxxx	

Reason for the EOL notice

These changes will enable Finisar to continue offering the highest performance products while maintaining competitiveness in the 10GBASE-SR SFP+ marketplace, and ensure continuity of supply.

Detailed Description of Change

The new generation of Finisar's 10GBASE-SR SFP+ transceivers provides improved mechanical design and lower power consumption. The Table below shows the main advantages of the FTLX8574D3Bxx over the old generation equivalent parts.

Description	857 0/1	857 <u>4</u>	
Finisar's designed,	Laser driver (LD)	LD, PA, and uP	
integrated single IC	Post-Amp (PA)	LD, PA, and up	
Optical Sub-Assemblies	TO-can	Chip-on-flex	
Min. Operating Case Temp.	0°C	-5°C	
Max Power Consumption	~0.7W	~0.5W	
EMI Collar	Wrap around	Laser-welded	
Mechanical Nose Septum		Improved finger-access	

End of Life Dates

All last time buy purchase orders must be received by July 15, 2016. The last time shipment date will be January 15, 2017, or earlier.

EOL #16.001 FINISAR

Order Acceptance/Change Conditions

Any orders with a requested ship date after July 15, 2016 will be non-cancelable and non-returnable (NCNR). The words "non-cancelable, non-returnable" must be clearly indicated on these orders. These orders cannot be changed, rescheduled, or cancelled.

RMA Replacements

After July 15, 2016, Finisar reserves the right to replace any of the discontinued FTLX8570D3Bxx and FTLX8571D3Bxx products listed above returned under RMA (Return Material Authorization) with equivalent FTLX8574D3Bxx parts, or with a credit (also in the case of the FTLX8572D3Bxx), if it is deemed to be Finisar responsibility.

Please do not hesitate to call your local distributor, rep, or local Finisar sales manager for any additional information you may need.

Finisar Corporation 1389 Moffett Park Drive Sunnyvale, CA 94089-1133 Tel. (408) 548-1000 / Fax (408) 541-6138 sales@finisar.com www.finisar.com