

Issue date: July 3, 2020 PTN No.: 1020001

Takashi Shimane Division Manager Wafer Process QC dept. WP Control Division WP Prodcution HQ ROHM Co., Ltd.

Notification of Product Discontinuance

Dear Valued Customer

This letter intends as a formal notification that ROHM Co., Ltd. is discontinuing the production of the following product. We acknowledges the obligation to promptly inform our customers of the intent to exit products to enable out customers the ability to prepare for alternatives and/or assist in our product portfolio renewal process.

It would be very appreciated if you could your reply by October 1, 2021

Your early reply in this regard would be very much appreciated.

| Product category | Affected part number(s) | Suggested replacement product | |
|---|---------------------------------|-------------------------------|--|
| LSI | See below | N/A | |
| Reason for discontinuance | | | |
| ROHM is obsoleting those products due to low demand which increases the cost of maintaining its production. | | | |
| Product discontinuance date | | | |
| November 1, 2021 | | | |
| Order after discontinuance | | | |
| Last Time Buy orders must be | received by October 1, 2021. No | cancellation accepted. | |

REPLY TO ROHM

To:Yuji Shimizu WP Control Division WP production headquarters ROHM Co., Ltd.

* Please check (∨).

BD6671FM-BJE2

BD4210EKN-E2

| _ • | rease check () |
|-----|---|
| | 1. Accept discontinuation |
| | 2. Accept discontinuance with written conditions below: |
| | |
| | |
| | |

Name (TYPE): Date: Department : Company : Signature : RGTSZ22304·04·002 Part Numbers: BD2041AFJ-BJE2 BD6671FM-E2 BD4211FV-E2 BD9767FV-E2 BD2041AFJ-BZE2 BD6706FV-E2 BD6015GU-E2 BD9767FV-FE2 BD2041AFJ-DE2 BD6709FS-E2 BD6020GU-E2 BD9881FV-E2 BD2041AFJ-E2 BD6709FS-GE2 BD6030GLS-E2 BD9825FV-E2 BD2042AFJ-BJE2 BD6709JFS-E2 BD6058GU-E2 BD9882F-E2 BD2042AFJ-BZE2 BD6709NFS-E2 BD7880MUV-E2 BD9882F-PE2 BD2042AFJ-E2 BD7628F-E2 BD6059EKN-E2 BD9882FV-BZE2 BD2045AFJ-ME2 BD7956FS NCL055K-ME2 BD9882FV-E2 BD2045AFJ-BZE2 BD7956FS-BZE2 JCM5053-E2 BD9882FV-RE2 BD2045AFJ-E2 BD7956FS-DE2 JCM5053E-E2 BD9886FV-BZE2 BD2052AFJ-BZE2 BD7956FS-E2 BD6692FS-E2 BD9886FV-E2 BD2052AFJ-E2 BD7996EFV-E2 BD6718FS-E2 BD9886FV-GE2 BD2052AFJ-HVE2 BD7960FM-E2 BD6718FV-E2 BD9886FV-PE2 BD2052AFJ-ME2 BD7960FM-ME2 BD6718FV-TE2 BD9886FV-RE2 BD2055AFJ-ME2 BD9850FVM-MTR BD6719FV-E2 BD9887FS-E2 BD2061AFJ-BJE2 BD9850FVM-TR BD6719FV-GE2 BD9889FV-E2 BD2061AFJ-BZE2 BD2046AFJ-BZE2 BD6792FM-E2 BD9890F-E2 BD2061AFJ-BZRE2 BD2046AFJ-E2 BD6903EFV-E2 BD9890FV-BZE2 BD2061AFJ-E2 BD2056AFJ-BZE2 BD7628FVM-TR BD9890FV-E2 BD3401KS2 BD2056AFJ-E2 BD7902CFS-E2 BD9892K-E2 BD3427K BD3520FVM-TR BD7902FS-E2 BD9892K-GE2 BD3427K-BJ BD3521FVM-TR BD7902HFS-E2 BD9893F-E2 BD3427K-E2 BD3806AFS-E2 RS2004FS-E2 BD9893F-GE2 BD3429K-E2 BD3806FS-E2 BD7907FS-E2 BD9895FV-E2 BD3451KS BD3808AFS-E2 SD2003-E2 BD9896FV-E2 BD3504FVM-FTR BD3808FS-E2 BD7908FS-E2 BD9896FV-GE2 BD3504FVM-TR BD3809FS BD7909FS-E2 BD9897FS BD3823FV-E2 BD3809FS-E2 BD7950FS-E2 BD9897FS-BZE2 BD3823FV-ME2 BD3824FS-E2 BD7954FS-E2 BD9897FS-E2 BD3980F-BZE2 BD3827K-E2 BD7957FS-DE2 BD9897FS-GE2 BD3980F-E2 BD3850FS-E2 BD7957FS-E2 BD9897FS-LE2 BD6517F-BZE2 BD3881FV-E2 BD7966EKV BD9218FM-E2 BD6517F-E2 BD3896FV-E2 BD6120ACH-3BW RS2005FS-E2 BD6519FJ-BJE2 BD3896FV-FE2 BD7997FS-E2 BD6519FJ-BZE2 BD3897FVM-TR BD8120FP-E2 BD6519FJ-E2 BD3897FV-E2 BD8201FM-E2 BD6524HFV-BZGTR BD3897FV-TE2 BD8202EFV-E2 BD6524HFV-BZTR BD3898HFN-GTR BD8541NV-E2 BD6524HFV-TR BD3917HFN-TR BD8691FVM-TR

BD9222FV-E2