

### 1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.	
SBU PG PUG Type					
01 002 042 0000000585	See list below	Circuit Protection	CSO Clip		
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)					

List of part numbers a	ffected		
0751.0500	0751.0501	0751.0502	0751.0503
0751.0505	0751.0506	0751.0507	0751.0508
3-111-506	3-111-507	3-124-244	3-124-245

### 2 Type of change

Change of material

# 3 Detailed description of change

The material of the CSO series fuse clip changes to a different copper alloy. Fuse clips manufactured with the new material can be identified by a mark "B1" or "B2" on the clip. This change has no effect on the rating and the approval of the fuse clip.

Old material	New material
Copper alloy	Different copper alloy, which may lead to a higher clip
	temperature by approximately 15K.
Old product appearance	New product appearance
	B1

### 4 Reason of change

There is a shortage of the old raw material due to force majeure.

#### 5 Release date

The change takes effect in week 08/2022 (Date code 2208 or higher on label).

## 6 Impact of change and recommended action

Form Yes No action required

Fit No -

Function Yes Please consider the impact of higher worst-case clip temperature

in your application

Manufacturing No Label No Packaging No -

### 7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	CSO Clip

Product Change Notification			PCN CSO material change				
owner	creation date	release date	released by	change order no	rev	page	D10-061-218
kesslema	19.11.2021	19.11.2021	schulejo	2022915	В	1 of 1	