NO: CON - 082 **DATE:** March 2018	**PRODUCT:** XP3B – Probe Pins **TYPE:** [Notice Type] Discontinuation

XP3B Probe Pins - Discontinuation

Omron will discontinue **_all_ XP3B** probe pins due to a diminishing global demand. There are no direct replacements for these probe pins. The models to be discontinued include, but are not limited to the models listed below. Should you have any questions, please communicate with the Connector Product Manager

LAST Order date (Last Time Buy Date)
February 28, 2019

Product Discontinuation	Suggested Replacement
XP3B Probe Pins	
Model All XP3B Probe Pins	**No suggested models**-

XP3B Details of Applicable Models:

Discontinued Models	Suggested Replacement	Discontinued Models	Suggested Replacement
XP3B-3029-5050-1-D/D	No recommended replacement	XP3B-3029-5050-1-S/S	No recommended replacement
XP3B-3029-5050-1-D/R	No recommended replacement	XP3B-3829-5050-1-D/D	No recommended replacement
XP3B-3029-5050-1-D/S	No recommended replacement	XP3B-3829-5050-1-D/R	No recommended replacement
XP3B-3029-5050-1-R/D	No recommended replacement	XP3B-3829-5050-1-D/S	No recommended replacement
XP3B-3029-5050-1-R/R	No recommended replacement	XP3B-3829-5050-1-R/R	No recommended replacement
XP3B-3029-5050-1-R/S	No recommended replacement	XP3B-3829-5050-1-S/R	No recommended replacement
XP3B-3029-5050-1-S/D	No recommended replacement	XP3B-3829-5050-1-S/S	No recommended replacement
XP3B-3029-5050-1-S/R	No recommended replacement		

* Sales teams should communicate this discontinuation with their OEM's and CEM's.
For further technical support and any questions, please communicate with Product Marketing.