DISCONTINUATION NOTICE

December 24, 2016

This letter serves as a formal notification that TechNexion has discontinued a number of configuration options (Bluetooth/WiFi sub-part numbers) for the EDM Type 1 System on Module **EDM1-CF-IMX6** effective when our inventory level is depleted.

Affected Part Numbers and Substitutes:

Discontinued Part Number	Replacement Part Number
EDM1CFIMX6S10R512NI4GL2CBW	**EDM1IMX6SPR05E04BB** : with BCM43438 **EDM1IMX6SPR05E04BW** : with BCM4339
EDM1CFIMX6U10R1GBNI4GL2CBW	**EDM1IMX6UPR10E04BB** : with BCM43438 **EDM1IMX6UPR10E04BW** : with BCM4339
EDM1CFIMX6D10R1GBNI4GLS2CBW	**EDM1IMX6DPR10E04BB** : with BCM43438 **EDM1IMX6DPR10E04BW** : with BCM4339
EDM1CFIMX6Q10R2GBNI4GLS2CBW	**EDM1IMX6QPR20E04BB** : with BCM43438 **EDM1IMX6QPR20E04BW** : with BCM4339
EDM1CFIMX6S10R512NI4GL2CBWTE	**EDM1IMX6SPR05E04BBTE** : with BCM43438 **EDM1IMX6SPR05E04BWTE** : with BCM4339
EDM1CFIMX6U10R1GBNI4GL2CBWTE	**EDM1IMX6UPR10E04BBTE** : with BCM43438 **EDM1IMX6UPR10E04BWTE** : with BCM4339
EDM1CFIMX6D10R1GBNI4GLS2CBWTE	**EDM1IMX6DPR10E04BBTE** : with BCM43438 **EDM1IMX6DPR10E04BWTE** : with BCM4339
EDM1CFIMX6Q10R2GBNI4GLS2CBWTE	**EDM1IMX6QPR20E04BBTE** : with BCM43438 **EDM1IMX6QPR20E04BWTE** : with BCM4339

Important Information for Migration to Replacement Parts:

Hardware : Original product part number and Replacement part number both follow EDM Type 1 specifications. No hardware modification is required.

Software : The replacement part numbers contain a new Bluetooth / WiFi component which needs a new software driver + Firmware to work.

This support has been added in TechNexion software since the following releases:
Ubuntu : Ubuntu LTS 16.04 and beyond
Linux : Kernel 4.1.15 and beyond
Android : Lollipop 5.1 and beyond

Please contact with your TechNexion Representative for assistance with smooth transition to next generation products. Samples of the above replacement part numbers are available.

Sincerely,

Leo Liao
Product Manager