

050" × .100" Latch/Ejector, Right Angle, 4 Rows of Solder Tails

Issue Number:	784
Date:	March 21, 2011

Product Discontinuation

3M is discontinuing production of the 4-wall Tripolarized Header 810 Series with 4 rows of solder tails. Please note that this is not the standard version of the tripolarized header; this is a nonstandard product version that is rarely used. Demand for these products no longer justifies their continued production. Tech sheet TS0334 is impacted by this change.

Affected Part Numbers

SKU	Part Number	80610481147	81050-M00203	80001252479	81080-M50203-RB
80001207028	81020-M00203	80000901787	81050-M00203-RB	80001207986	81080-M60203
80000901522	81020-M00203-RB	80001207614	81050-M50203	80130030564	81100-M00203
80610487987	81020-M10203	80001252578	81050-M50203-RB	80000902041	81100-M00203-RB
80001207036	81020-M50203	80610463186	81050-M60203	80400009942	81100-M10203
80001207044	81020-M60203	80620117764	81060-M00203	80610468631	81100-M20203
80001207192	81026-M00203	80000901852	81060-M00203-RB	80400029122	81100-M50203
80000901563	81026-M00203-RB	80610489116	81060-M10203	80001206913	81100-M60203
80400011732	81026-M50203	80400013290	81060-M50203	N/A	81020-M50203-RB
80001207200	81026-M60203	80001207754	81060-M60203	N/A	81020-M60203-RB
80610463889	81036-M00203	80610469068	81068-M00203	N/A	81026-M50203-RB
80000901605	81036-M00203-RB	80000900300	81068-M00203-RB	N/A	81026-M60203-RB
80400011617	81036-M10203	80000901894	81068-M00203-RB	N/A	81036-M60203-RB
80400009918	81036-M50203	80610489124	81068-M10203	N/A	81040-M50203-RB
80001207341	81036-M50203-RB	80000911083	81068-M20203	N/A	81040-M60203-RB
80001211574	81036-M50203-RB	80610465231	81068-M50203	N/A	81050-M60203-RB
80001207358	81036-M60203	80001152505	81068-M50203-RB	N/A	81060-M50203-RB
80001207473	81040-M00203	80400005478	81068-M60203	N/A	81060-M60203-RB
80400010064	81040-M00203	80000917916	81068-M60203-RB	N/A	81080-M60203-RB
80000901696	81040-M00203-RB	80130027016	81080-M00203	N/A	81100-M50203-RB
80001207481	81040-M50203	80000901977	81080-M00203-RB	N/A	81100-M60203-RB
80001207499	81040-M60203	80400029114	81080-M50203		

*This list is complete to the best of our knowledge; however, there may also be custom parts that utilize this product as a base. These custom products will also be discontinued.

Last Time Buys

3M will offer last time buy opportunities for all parts listed in the table above through May 31, 2011.



Product Discontinuation Notice 3M[™] Four-Wall, Tripolarized Header 810 Series, 050" × .100" Latch/Ejector, Right Angle, 4 Rows of Solder Tails

Replacements

A direct replacement does not exist for this product. However, the standard 2-row Right Angle Through-Hole Headers in the 810 product series remain available on TS-0253. These headers mate to the same cable-mount socket (TS-0254; 820 Series), and will serve the same general purpose. However, the customer must determine whether the product is suited for their intended application.

<u>Please note that the PCB mounting pattern will be different for these 2-row headers as compared to the</u> <u>4-row headers marked for discontinuation in this notice</u>. For dimensions and board configuration patterns, please refer to **TS-0253**.

Contact Information

In the USA 3M US Customer Service 800-225-5373

Outside the USA

Please contact your local 3M subsidiary or authorized distributor. Visit www.3Mconnector.com and click "Where to Buy."

3M is a trademark of 3M Company

Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of one year from the time of purchase. 3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. Except where prohibited by law, 3M will not be liable for any indirect, special, incidental or consequential loss or damage arising from this 3M product, regardless of the legal theory asserted.

3M

Electronic Solutions Division Interconnect Products 6801 River Place Blvd. Austin, TX 78726-9000 1-800-225-5373 www.3Mconnectors.com © 3M 2

© 3M 2011 All Rights Reserved.