

Australia Headquarters

Unit 7, 103 Sargents Road, Minchinbury, NSW 2270 www.4dsystems.com.au Ph +61 2 9625 9714 | Fax +61 2 8834 0747 ABN 85 003 869 56

Date: August 7th, 2019

Subject: Product change notification

Dear Customer,

4D Systems is making some changes to the individual parts included in some of its Intelligent Display Module Starter Kits.

The uUSB-PA5-II will be included in all uLCD branded starter kits instead of the 4D-UPA. This does not affect the functionality of the starter kits.

During this transition it is possible that you will receive a starter kit that either includes a 4D-UPA or a uUSB-PA5-II programming adaptor in the kit. Both programming adaptors provide the same functionality and do not affect the way that you work with the display module during your development.

The enclosed table outlines the affected products and milestone dates.

We are consistently dedicated to providing our customers with excellent products and services. If you have any questions, please contact your 4D Systems Account Manager.

Please feel free to contact us if you have any questions or concerns regarding this announcement.

Sincerely,

Markku Riihonen Global Products and Business Development Manager **4D Systems**



Australia Headquarters

Unit 7, 103 Sargents Road, Minchinbury, NSW 2270 www.4dsystems.com.au Ph +61 2 9625 9714 l Fax +61 2 8834 0747 ABN 85 003 869 56

New Part Numbers: Part Numbers will remain identical

Description of Change: All Starter Kits for uLCD products (non gen4 starter kits) will contain one piece of uUSB-PA5-II programming adaptor instead of one piece of the 4D-UPA and 150mm 30-way FFC Cable.

Impacts to Data Sheet: Content changes to section: "Hardware Tools"

Other Documents Affected: None

Reason for Change: Simplification of workflow with uLCD Starter Kits

Estimated First Ship Date: 7 August 2019

Affected Product	Related Product	Change	Last time buy date	Last time delivery date
All SK-XXXX that exclude gen4 in the part number.	N/A	Content change from 4D-UPA to uUSB-PA5-II	July 2019	July 2019

Affected Part numbers:
SK-96G2
SK-128G2
SK-160G2
SK-144G2
SK-24PTU
SK-28PTU
SK-32PTU
SK-220RD
SK-35DT
SK-43D
SK-43DT
SK-43DCT
SK-70DT
SK-96G2-AR
SK-128G2-AR



Australia Headquarters

Unit 7, 103 Sargents Road, Minchinbury, NSW 2270 www.4dsystems.com.au Ph +61 2 9625 9714 | Fax +61 2 8834 0747 ABN 85 003 869 56

SK-160G2-AR
SK-144G2-AR
SK-24PTU-AR
SK-28PTU-AR
SK-32PTU-AR
SK-220RD-AR
SK-35DT-AR
SK-43D-AR
SK-43DT-AR
SK-43DCT-AR
SK-70DT-AR
SK-24PTU-PI
SK-28PTU-PI
SK-32PTU-PI
SK-220RD-PI
SK-35DT-PI
SK-43D-PI
SK-43DT-PI
SK-43DCT-PI
SK-70DT-PI
SK-uVGA-III
SK-32028-P1
SK-32028-P1T
SK-43PT
SK-43PT-AR
SK-43PT-PI
SK-4Duino-24
SK-4Duino-24-2

