ams AG
Tobelbader Strasse 30
8141 Premstaetten
Austria

T +43 3136 500-0 F +43 3136 525-01 sensors@ams.com www.ams.com



Premstätten, June 13, 2017

Product discontinuation

(AS5035/AS5163/AS5263/AS5011/AS3931/AS8506C/AS8515/AS8530)

Dear Customer,

Although product lifetime and delivery period at ams AG are longer than at many other suppliers in the semiconductors industry we are sorry to announce that further production of products listed on page 2 cannot be supported any longer.

Reason for that is that the total demand for these products has declined to such a level that an economic production can no longer be warranted. We therefore ask for your kind cooperation in the phasing out of the product. To make the phase out as convenient as possible for you, we are pleased to offer the following conditions:

Last possible order placement: Dec.31, 2017
 Last shipment: June 30, 2018

LTB orders to be placed in multiples of packing units.

As multiple customers are ordering these devices the respective order quantities will be coordinated by ams AG. Thank you very much for your understanding.

For any further questions please feel free to contact me.

Best regards,

Dr Dietmar Gleispach

ams AG

Director Operations Division EAS



Affected products

	ordering codes
AS5035	AS5035
	AS5035-ASST
	AS5035-Z
	AS5035-Z (T&R)
	AS5035-Z (Tube)
AS5163	AS5163-HTSM
	AS5163-HTSP
	AS5163M-HTSP
AS5263	AS5263
	AS5263-HQFM
	AS5263-HQFT
AS5011	AS5011 (T&R)
AS3931	AS3931
	AS3931(Tube)
	AS3931-T
	AS3931-Z
	AS3931-ZTSM
	AS3931-ZTST
	AS3931-ZTSU
AS8506C	AS8506C-BQFM
	AS8506C-BQFM-A
	AS8506C-BQFM-S
	AS8506C-BQFP
	AS8506C-BQFP-A
	AS8506C-BQFP-S
AS8515	AS8515-ZMFM
	AS8515-ZMFP
AS8530	AS8530-ASOM
	AS8530-ASOP