

**PCN: V17-001-48475412-0A**

## Product Change Notice

**Issue Date: 30th Aug 2017**

**Change Type:**

Introduction of new die for part numbers listed below.

**Parts Affected:**

Part numbers affected by the change are:-

HLMP-DB25-B0000	QLMP-DS49-E0000	HLMP-DS25-F0000
HLMP-KA45-E0000	HLMP-KA45-J0000	HLMP-DS25-F00DD
HLMP-NS30-J0000	HLMP-NS30-J00DD	HLMP-KB45-A0000
HLMP-NS30-NQ0DD	HLMP-NS30-RU0DD	

**Description and Extent of Change:**

The new die will replace the existing die for all the part numbers above.

**Reasons for Change:**

Obsolescence of existing die.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There is no change in the fit, form and function of the affected part numbers.

**Effective Date of Change:**

Broadcom Limited will commence shipment of these part numbers with the new die effective 30th Nov 2017. Shipment may contain product with existing or new die.

**Qualification Data:**

Qualification data will be made available upon request.

---

These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom Limited field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.