

PRODUCT OBSOLESCENCE MEMO

REVISED MARCH 21, 2022

Select Bourns® Custom Magnetics Products to be Discontinued

Riverside, California – January 6, 2022 – In accordance with our ongoing product life cycle management procedure, Bourns will transfer select custom Magnetics products to an End of Product Life status on June 20, 2022. A lack of sales volume and diminishing demand necessitates this action.

| | | Obsolete Part Numbers | | |
|--------------|--------------|-----------------------|--------------|--------------|
| TMS60149CT | TMS63780CT | TMA60373CS | TMS63089CT | TMA60442CS-L |
| TMS60054CT | TMS81023CT | TMA60067CT | BA50979CS | TMA60443CS |
| TMA60105CT-1 | TMS51702CT | TMA80082CF | TMA60414CS | TMA60443CS-L |
| TMA60106CT-1 | TMW10042CF | TMP60352CS | TMA60482CS | TMA60477CT |
| TMS93082CS | TMS81027CT | TMS60476CT | TMS61379CT | TMA60481CS |
| TMS93885CS | TMS63892CT | TMS60541CT | BA60721CT | TMA60484CS |
| TMP90088CS | TMS63949CT | TMS60641CT | BA60866CT | TMA60485CS |
| BA51004CT | TMS63951CS | TMS61062CT | BA60866CT-D2 | TMA60494CT |
| BA70349CF-1 | TMS63973CT | TMS80088CS | BA60867CT | TMA60494CT-1 |
| TMA80167CF | TMS63990CT | TMS81054CT | BA60867CT-D3 | TMA60494CT-3 |
| TMS51734CF | TMS80079CT | — BS64042CS —) | BA70310CF | TMA60501CS |
| TMA60168CT | TMS80079CT-1 | TMS50542CT | BA70310CF-1 | TMA60501CS-1 |
| BA80239CF | TMS63844CT | BS64031CS | TMA50698CF | TMA60501CS-2 |
| TMA50545CF | TMS63733CT | TMS63007CT | TMA50700CF | TMA60501CS-5 |
| TMA50546CF | TMS63738CT | TMS63763CT | TMA50700CF-1 | TMS62478CS |
| TMA50547CF | TMS63745CT | BS64010CS | TMA50700CF-2 | TMS63469CT |
| TMS63464CT | TMS63663CT | TMS51655CT | TMA50701CF | |
| BA80205CT | TMS63611CS | TMS63008CT | TMA50701CF-1 | |
| TMS20102CS | BA60827CS | TMS63467CT | TMA50701CF-2 | |
| TMS63890CT | TMA50013CS | TMS63642CT | TMA60442CS | |

Regrettably, no replacement part numbers are available at this time. Customers may continue to purchase these components during the End of Product Life transition period between now and June 20, 2022. Orders for this discontinued components during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: *June 20, 2022*Last time ship date: *December 20, 2022*

If you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.

IC219954REV

| P/N | Туре | Comments |
|--------------|-------------------|----------|
| TMS60149CT | Through-hole | |
| TMS60054CT | Through-hole | |
| TMA60105CT-1 | Through-hole | |
| TMA60106CT-1 | Through-hole | |
| TMS93082CS | Surface mount | |
| TMS93885CS | Surface mount | |
| TMP90088CS | Surface mount | |
| BA51004CT | Through-hole | |
| BA70349CF-1 | Flying Lead Style | |
| TMA80167CF | Flying Lead Style | |
| TMS51734CF | Flying Lead Style | |
| TMA60168CT | Through-hole | |
| BA80239CF | Flying Lead Style | |
| TMA50545CF | Flying Lead Style | |
| TMA50546CF | Flying Lead Style | |
| TMA50547CF | Flying Lead Style | |
| TMS63464CT | Through-hole | |
| BA80205CT | Through-hole | |
| TMS20102CS | Surface mount | |
| TMS63890CT | Through-hole | |
| TMS63780CT | Through-hole | |
| TMS81023CT | Through-hole | |
| TMS51702CT | Through-hole | |
| TMW10042CF | Flying Lead Style | |
| TMS81027CT | Through-hole | |
| TMS63892CT | Through-hole | |
| TMS63949CT | Through-hole | |
| TMS63951CS | Surface mount | |
| TMS63973CT | Through-hole | |
| TMS63990CT | Through-hole | |
| TMS80079CT | Through-hole | |
| TMS80079CT-1 | Through-hole | |
| TMS63844CT | Through-hole | |
| TMS63733CT | Through-hole | |
| TMS63738CT | Through-hole | |
| TMS63745CT | Through-hole | |
| TMS63663CT | Through-hole | |
| TMS63611CS | Surface mount | |
| BA60827CS | Surface mount | |
| TMA50013CS | Surface mount | |
| TMA60373CS | Surface mount | |
| TMA60067CT | Through-hole | |
| TMA80082CF | Flying Lead Style | |
| TMP60352CS | Surface mount | |
| | | |

| TMS60476CT | Through-hole |
|------------|---------------|
| TMS60541CT | Through-hole |
| TMS60641CT | Through-hole |
| TMS61062CT | Through-hole |
| TMS80088CS | Surface mount |
| TMS81054CT | Through-hole |

BS64042CS removed from this announcement 3/21/22

BS64042CS Surface mount

Through-hole TMS50542CT BS64031CS Surface mount TMS63007CT Through-hole Through-hole TMS63763CT BS64010CS Surface mount Through-hole TMS51655CT Through-hole TMS63008CT Through-hole TMS63467CT Through-hole TMS63642CT TMS63089CT Through-hole BA50979CS Surface mount Surface mount TMA60414CS Surface mount TMA60482CS Through-hole TMS61379CT BA60721CT Through-hole Through-hole BA60866CT Through-hole BA60866CT-D2 BA60867CT Through-hole BA60867CT-D3 Through-hole BA70310CF Flying Lead Style BA70310CF-1 Flying Lead Style TMA50698CF Flying Lead Style TMA50700CF Flying Lead Style Flying Lead Style TMA50700CF-1 TMA50700CF-2 Flying Lead Style TMA50701CF Flying Lead Style TMA50701CF-1 Flying Lead Style TMA50701CF-2 Flying Lead Style Surface mount TMA60442CS TMA60442CS-L Surface mount TMA60443CS Surface mount TMA60443CS-L Surface mount TMA60477CT Through-hole TMA60481CS Surface mount TMA60484CS Surface mount Surface mount TMA60485CS

| TMA60494CT | Through-hole |
|--------------|---------------|
| TMA60494CT-1 | Through-hole |
| TMA60494CT-3 | Through-hole |
| TMA60501CS | Surface mount |
| TMA60501CS-1 | Surface mount |
| TMA60501CS-2 | Surface mount |
| TMA60501CS-5 | Surface mount |
| TMS62478CS | Surface mount |
| TMS63469CT | Through-hole |