

Product Change Notification

Date December 19, 2019

Product

Connect IT 4/16/48/Mini

	New firmware version 19.11.72.58 available for all Connect IT products. This is a major scheduled production release. Digi requires all customers upgrade their Connect IT products to firmware v19.11.72.58
--	--

	New Firmware Version 19.11.72.58 provides:
	Important security fixes
Reason for Change	Bug fixes
	New features
	Enhancements
	See Release Notes for more details.

Product Notice	A new stable firmware version has been released for the Connect IT products, version 19.11.72.58. Use the link below to view the full list of changes, features, and fixes included in the new firmware.	
	<u>Connect IT Release Notes</u>	
	To take advantage of the new features listed below, you must take action to upgrade your device. Refer to the instructions to upgrade your firmware in the release notes above for more information.	
	Any questions or concerns about the new firmware, or for assistance upgrading your device(s), please contact the Digi Support team at <u>tech.support@digi.com</u> .	

Affected Part Numbers	IT16-1002, IT48-1002, IT01-M100, ASB-5402-RM
Anected Full Humbers	1110 1002, 11 10 1002, 1101 11100, 10D 0 102 101

Timing of Change	Effective Immediately