

Product Change Notification

Date March 15, 2021

Product

Connect IT 4/16/48/Mini

Description of change

New firmware version 21.2.39.67 available for all Connect IT products. This is a major production release. Digi recommends all customers update their Connect IT products to firmware v21.2.39.67

Reason for Change

New Firmware Version 21.2.39.67 provides:

- **New Features**
- Enhancements
- **Bug Fixes**
- **Security Fixes**

See Release Notes for more details.

Product Notice

A new stable firmware version has been released for the Connect IT products, version 21.2.39.67. Use the link below to view the full list of changes, features, and fixes included in the new firmware.

Connect IT Release Notes

To take advantage of the new features, you must take action to update your **device.** Refer to the instructions to update your firmware in the release notes above for more information.

Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team at tech.support@digi.com.

Affected Part Numbers | IT16-1002, IT48-1002, IT01-M100, ASB-5402-RM

Timing of Change	Effective Immediately