

Date: September 28, 2020
To: Bussmann series renewable fuses and fusible links customers
Subject: End-of-life notification

Dear valued customer:

Effective immediately, the Bussmann™ series products listed below are obsolete. Recommended replacements are provided. For replacement fusible links, the recommended replacement is to move up to Class RK1 fuses. For select applications, it may be preferred to move to Class RK5 fuses.

Material #	EAN/UPC	Recommended Replacement	Note
LKN-110	051712315845	LPN-RK-110SP	Full Fuse, not internal link
LKN-125	051712131254	LPN-RK-125SP	Full Fuse, not internal link
LKN-125B	051712577915	LPN-RK-125SP	Full Fuse, not internal link
LKN-15	051712130158	LPN-RK-15SP	Full Fuse, not internal link
LKN-175	051712131759	LPN-RK-175SP	Full Fuse, not internal link
LKN-20	051712130202	LPN-RK-20SP	Full Fuse, not internal link
LKN-200B	051712577922	LPN-RK-200SP	Full Fuse, not internal link
LKN-225	051712132251	LPN-RK-225SP	Full Fuse, not internal link
LKN-25	051712130257	LPN-RK-25SP	Full Fuse, not internal link
LKN-250	051712132503	LPN-RK-250SP	Full Fuse, not internal link
LKN-3	051712130035	LPN-RK-3SP	Full Fuse, not internal link
LKN-35	051712130356	LPN-RK-35SP	Full Fuse, not internal link
LKN-350	051712133500	LPN-RK-350SP	Full Fuse, not internal link
LKN-40	051712130400	LPN-RK-40SP	Full Fuse, not internal link
LKN-5	051712130059	LPN-RK-5SP	Full Fuse, not internal link
LKN-50	051712130509	LPN-RK-50SP	Full Fuse, not internal link
LKN-500	051712135009	LPN-RK-500SP	Full Fuse, not internal link
LKN-500B	051712587600	LPN-RK-500SP	Full Fuse, not internal link
LKN-6	051712130066	LPN-RK-6SP	Full Fuse, not internal link
LKN-600	051712136006	LPN-RK-600SP	Full Fuse, not internal link
LKN-70	051712130707	LPN-RK-70SP	Full Fuse, not internal link
LKN-80B	051712577908	LPN-RK-80SP	Full Fuse, not internal link
LKS-110	051712141109	LPS-RK-110SP	Full Fuse, not internal link
LKS-12	051712140126	LPS-RK-12SP	Full Fuse, not internal link
LKS-125	051712141253	LPS-RK-125SP	Full Fuse, not internal link
LKS-150	051712141505	LPS-RK-150SP	Full Fuse, not internal link
LKS-175	051712141758	LPS-RK-175SP	Full Fuse, not internal link
LKS-225	051712140164	LPS-RK-225SP	Full Fuse, not internal link

Material #	EAN/UPC	Recommended Replacement	Note
LKS-25	051712140256	LPS-RK-25SP	Full Fuse, not internal link
LKS-250	051712142502	LPS-RK-250SP	Full Fuse, not internal link
LKS-3	051712140034	LPS-RK-3SP	Full Fuse, not internal link
LKS-300	051712143004	LPS-RK-300SP	Full Fuse, not internal link
LKS-35	051712140355	LPS-RK-35SP	Full Fuse, not internal link
LKS-350	051712143509	LPS-RK-350SP	Full Fuse, not internal link
LKS-45	051712140454	LPS-RK-45SP	Full Fuse, not internal link
LKS-5	051712140058	LPS-RK-5SP	Full Fuse, not internal link
LKS-50	051712140508	LPS-RK-50SP	Full Fuse, not internal link
LKS-500	051712145008	LPS-RK-500SP	Full Fuse, not internal link
LKS-6	051712140065	LPS-RK-6SP	Full Fuse, not internal link
LKS-70	051712140706	LPS-RK-70SP	Full Fuse, not internal link
LKS-80	051712140805	LPS-RK-80SP	Full Fuse, not internal link
LKS-90	051712140904	LPS-RK-90SP	Full Fuse, not internal link
REN-100	051712200103	LPN-RK-100SP	
REN-200	051712102001	LPN-RK-200SP	
REN-25	051712100250	LPN-RK-25SP	
REN-35	051712100359	LPN-RK-35SP	
REN-40	051712100403	LPN-RK-40SP	
REN-45	051712100458	LPN-RK-45SP	
REN-5	051712100052	LPN-RK-5SP	
REN-50	051712100502	LPN-RK-50SP	
REN-7	051712100083	LPN-RK-7SP	
RES-100	051712111003	LPS-RK-100SP	
RES-125	051712111256	LPS-RK-125SP	
RES-3	051712110037	LPS-RK-3SP	
RES-5	051712110051	LPS-RK-5SP	
RES-50	051712110501	LPS-RK-50SP	
RES-60	051712110600	LPS-RK-60SP	

Any inventory of existing product is saleable and should not be returned.

If you have any questions concerning this notice, contact FuseTech@Eaton.com or your local Bussmann series product sales representative.

Kind regards,



Greg Brossier
Product manager, power conversion and energy storage protection
Bussmann series products