

Eaton Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN19023 12/4/2019

CLASSIFICATION OF CHANGE:

End of Life

DESCRIPTION OF CHANGE:

All solder dipped leads within the PC Tron fuse family will no longer be manufactured.

REASON FOR CHANGE:

Product has reached end of life.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Parts affected by the EOL can be replaced with the non-solder dipped standard parts. There is no difference between the solder dipped leads and the standard product electrical performance.

PARTS FAMILIES AFFECTED

Please see the following page for EOL and recommended replacements

TIME SCHEDULE:

Last time buy offered through 12/31/19 Final shipment date on or before 2/28/2020.

ISSUED BY:

Jenan Krouchick Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html

| Solder Dipped Catalog Number | Recommended Standard Replacement Catalog Number |
|---------------------------------|--|
| BK/PCB-1-1/2-SD | BK/PCB-1-1/2-R |
| BK/PCB-1/2-SD | BK/PCB-1/2-R |
| BK/PCB-1-SD | BK/PCB-1-R |
| BK/PCB-2-1/2-SD | BK/PCB-2-1/2-R |
| BK/PCB-2-SD | BK/PCB-2-R |
| BK/PCB-3/4-SD | BK/PCB-3/4-R |
| BK/PCB-3-SD | BK/PCB-3-R |
| BK/PCC-1-1/2-SD | BK/PCC-1-1/2-R |
| BK/PCC-3-SD | BK/PCC-3-R |
| BK/PCD-5-SD | BK/PCD-5-R |
| BK/PCE-5-SD | BK/PCE-5-R |
| BK/PCH-2-1/2-SD | BK/PCH-2-1/2-R |
| BK/PCH-3-SD | BK/PCH-3-R |
| BK/PCH-4-SD | BK/PCH-4-R |
| BK-PCL-5-SD | BK-PCL-5-R |
| PCH-3-SD | PCH-3-R |
| TR/PCB-1-1/2-SD | TR/PCB-1-1/2-R |
| TR/PCB-1-SD | TR/PCB-1-R |
| TR/PCB-3-SD | TR/PCB-3-R |
| 89096-005 | PCC-1-R |
| 89096-013 | PCB-3-R |
| 89096-015 | PCD-5-R |