

Product Change Notice

Date:	December 22, 2020
Overview:	Select part numbers are being discontinued; technical equivalents are available for most
Reason for Change:	Continued optimization of our production processes and streamlining of our product portfolio
Affected Part No(s):	Please see part number listing with technical equivalents on page 2 of this PCN
Design Change Detail:	Select part numbers are being discontinued due to our ongoing efforts to optimize our production processes and streamline our product portfolio; technical equivalents are available for most
Effective Date:	The discontinued products are available for purchase until January 22, 2021 after which we suggest moving to the technical equivalents, where available
Last Time Buy Deadline:	January 22, 2021
Pricing:	Please see current price file
ebm-papst employee:	Jeannine Zenobi
Attachments:	Part number listing with technical equivalents
Comments:	For part numbers without a technical equivalent, please contact us so we can make a recommendation based on the application

Affected Part Numbers with Technical Equivalents

Part Number	Technical Alternative	Note(s)
3500	3606	Improved version, ball bearing
3506	3606	Improved version
3550	3556	Ball bearing
3600	3606	Ball bearing
4500N	4600N	Improved version
4530N	4600N	Improved version
4536Z	4606Z	Improved version
4600TZ	No direct replacement	
4656EZU-066	4656EZU	
4656TA	No direct replacement	
4656ZWR-903	No direct replacement	
4666ZW	No direct replacement	
4800N	4800Z	Different blowing direction
4800X	4800Z	Different blowing direction
4806Z	4800Z	Sleeve bearing, smaller temp range
8500A	8500N	
8500V	8500N	
8506A	8506N	Different blowing direction
8524VW	8526VWR-686	Ball bearing, acid protection
8550TV	No direct replacement	
8556TV	No direct replacement	
8560VW	8560N	Connection wire 310mm
8800N	8500N	Improved version
8856N	8556N	Improved version
8880V	8880N	

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. - Orig, Released 08/28/14	Retention Period - 1 year	Dept. Owner - Sales/Marketing