

PCN - 11 123

Issue Date: November 03 2011

·	1				
Product Name:	Bergstik				
	Bergstik				
Product Manager:	Franck CHAPOUILLY				
Subject:	Product Cha	ange Notificatio	on		
Distribution:	Global Distr	ibution			
Type of Change:		sign Change			
Change Description:	option).	plex to duplex	NEW tail	in solder	with std housing (no more groove for latching
	Но	using change]	LD CONTRACTOR	
Reason for Change:	As a direct consequence of an un-repairable equipment breakdown, FCI can no longer support the supply of a limited ra of specific BergStik [™] part-numbers as per the list attached. This is mainly series 75844 - 75160 - 75168 - 76350 - 75188 76345 - 75189 - 75209 - 75210 Therefore, where-ever the application of these products allows, FCI proposes to supersede the affected series with FCI's standard series BergStik [™] products. See attached List for full cross reference. You can contact your sale representative Product Manager directly if you need any assistance in identifying a replacement part number, or want to consider other alternative options (such as latches options).				
Affected Parts:	See list attached				
Effective Date of Change:	November	04	2011		
Last Time Buy Date:	N/A	N/A	N/A		
Last Disty Return Date:	N/A	N/A	N/A		
Datasheet Attached?	No		1	1	
Qual/Test Data Attached?	No				
Samples Availability Date:	November	04	2011		
Available Alternatives?	No				
Questions?	Franck CHAPOUILLY Product Manager Ph: + 3 33 81 54 59 86 franck.chapouilly@fciconnect.com				