FINISAR

End of Life Notification EOL16.002 1000BaseT Gen 1 Copper SFP Transceiver

This document is an End of Life Notification (EOL) for certain SFP transceivers.

Affected Part Numbers and Recommended Replacement Part Numbers

The Finisar part numbers affected by this EOL along with the recommended replacement part number are as follows:

EOL Part Number	Suggested Replacement Part Number
FCLF-8520-3	FCLF8522P2BTL
FCLF-8520-3-xx	FCLF8522P2BTL-xx
FCLF-8521-3	FCLF8522P2BTL
FCLF-8521-3-xx	FCLF8522P2BTL-xx

End of Life Dates

All last time buy purchase orders must be received by Jul 29, 2016. The last time shipment date will be Jan 30, 2017.

Order Acceptance/Change Conditions

Any orders for the discontinued products listed above with a requested ship date after Apr 30, 2016 will be non-cancelable and non-returnable (**NCNR**). The words "non-cancelable, non-returnable" must be clearly indicated on these orders. These orders cannot be changed, rescheduled, or cancelled.

RMA Replacements

After April 30, 2016, Finisar reserves the right to replace any of the discontinued products listed above returned under RMA (Return Material Authorization) with a credit if it is deemed to be Finisar responsibility.

We apologize in advance for any inconvenience this may cause. This is necessary for Finisar to offer the highest performance products at the lowest possible price. Please do not hesitate to call on your local distributor, rep, or local Finisar sales manager for any additional information you need.

For More Information

Finisar Corporation

1389 Moffett Park Drive Sunnyvale, CA 94089-1133 Tel. (408) 548-1000 Fax (408) 541-6138 <u>sales@finisar.com</u> www.finisar.com