

10/18/2019

**Subject:** Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

| Type (Only Checked Changes Apply)    |                             |                     |                                 |
|--------------------------------------|-----------------------------|---------------------|---------------------------------|
| □ Production/assembly location       | □ Ma                        | terial              | ☐ End of Life w/ replacement    |
| ☑ Part Number/Ordering Code          | □ Pac                       | ckaging             | ☐ End of Life w/o replacement   |
| ☑ Country of Origin                  | $\square$ Pos               | int of Purchase     | ☐ Additional tool/refurbishment |
| ☐ Design (fit, form, function)       | $\square$ Pos               | int of Pick up      | ☐ Cost/Lead Time                |
| ☐ Engineering record (non-fit, form, | function) $\square$ Su      | pply Chain          | ☐ Process                       |
| Additional Information               |                             |                     |                                 |
| From:                                |                             | To:                 |                                 |
| Manufacturing location: France       | Manufacturing location: USA |                     |                                 |
| COO: France                          |                             | COO: USA            |                                 |
| HT Order Code: 155-30602             | HT Order Code: 157-00467    |                     |                                 |
|                                      |                             |                     |                                 |
| From:                                |                             | To:                 |                                 |
| Manufacturing location: France       |                             | Manufacturing locat | ion: USA                        |
| COO: France                          |                             | COO: USA            |                                 |
| HT Order Code: 157-00083             |                             | HT Order Code: 157  | 7-00380                         |
|                                      |                             |                     |                                 |
| Scope                                |                             |                     |                                 |
| HT PN / Ordering Code                | <b>Customer PN</b>          | (                   | Change Effective*               |
| 155-30602                            | 1436-1041-ND                | 1                   | /13/2019                        |
| 157-00083                            | 1436-1106-ND                | 1                   | /13/2019                        |
|                                      |                             |                     |                                 |

We ask that you please acknowledge this notification by 11/1/2019, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Kelsey Shrader Quality Project Engineer

<sup>\*</sup>Effective date is subject to change based on availability