HellermannTyton

September 1, 2017

Re: Change Notification for 155-12300 to 157-00252

To Our Valued Customer:

To better serve your business, we inform you of the following change.

HellermannTyton part number 155-12300 is no longer available. It is replaced by HellermannTyton part number 157-00252. The difference in these two items is:

Design optimization for improved performance

Our records show that your part number is 1436-1639-ND, 155-12300-ND and the last order was placed in 2017. We ask that future purchase orders be placed for the new HellermannTyton part number. Any open orders will be revised to the new part number.

Due to the urgency of this change, we ask that you acknowledge this notification within 10 business days. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative.

We appreciate your support in this change and thank you for your continued business.

Sincerely,

Kelsey Shrader Quality Project Engineer Office: 414 355 1130 x 8751

Email: kshrader@htamericas.com