# HIROSE ELECTRIC CO., LTD.

2-6-3 Nakagawa Chuoh, Tsuzuki-ku, Yokohama, JAPAN

# Impact on our products by some PPS compound products made by DIC Corporation that don't reach UL certification rating

Recently, DIC Corporation (Hereinafter DIC) announced that some PPS compound products don't reach the certification rating of Underwriters Laboratories (hereinafter UL) who is a third party safety science organization in the United States.

We are writing to inform you of the impact on our company and our actions.

#### 1 Our impacted products

Please refer to attached sheet.

They are not UL recognized connectors.

# 2 Applicable DIC material

DIC part number FZ-4020-A4 and FZ-4020-A4 BLACK.

At this moment UL certification of these two materials are not cancelled.

### 3 DIC explanation to our company at this moment

\*DIC has been recognizing that heat treatment (hereinafter annealing) of combustion test pieces was approved

prescription in the UL certification procedure.

And the applicable materials were annealed from the first application to UL

- \*After confirming with UL about the possibility of annealing, basically annealing treatment is not permitted prescription.
- \*Based on the view expressed by UL, we measured the combustibility value of the applicable materials that were not annealed.

DIC in-house test results revealed that the applicable materials don't meet the UL certification rating.

DIC plans to report this content to UL.

## 4 Shipment

We continue to receive orders and shipping the impacted products.

Since our impacted products are not UL recognized connectors, we will continue to produce and ship using the applicable materials.

Please contact our staff in case you wish to suspend shipping.

In case DIC UL certification is cancelled, the notation "UL94V-0" related to the applicable materials in the specification sheets and catalog will be deleted in sequence.

Please contact our staff in case you wish to replace the specification sheets that have already been delivered.

If there is a change in the situation, we will report it again.

If you should have any questions, please feel free to contact a Hirose business representative.

Your understanding and cooperation are highly appreciated.

■ Product list
Business430-21027-1\_Regarding DIC PPS compound products that don't reach UL certification rating

|                 | Product code                   | Part Number                                     | UL certification        |
|-----------------|--------------------------------|-------------------------------------------------|-------------------------|
| 1               | 580-1331-2-10                  | FH33J-16S-0.5SH(10)                             | status of connectors No |
| 2               | 580-1325-0-99                  | FH33MHJ-65S-0.4SH(99)                           | No                      |
| 3               | 580-1325-0-10                  | FH33MHJ-65S-0.4SH(10)                           | No                      |
| 4               | 580-1326-2-10                  | FH33J-12(6)SB-1SH(10)                           | No                      |
| 5               | 580-1326-2-99                  | FH33J-12(6)SB-1SH(99)                           | No                      |
| 6               | 580-1328-8-10                  | FH33J-12S-0.5SH(10)                             | No                      |
| 7               | 580-1328-8-99                  | FH33J-12S-0.5SH(99)                             | No                      |
| 8               | 580-1329-0-10                  | FH33J-4S-0.5SH(10)                              | No                      |
| 9               | 580-1329-0-99                  | FH33J-4S-0.5SH(99)                              | No                      |
| 10              | 580-1324-7-10                  | FH33J-10S-0.5SH(10)                             | No                      |
| 11              | 580-1324-7-10                  | FH33J-10S-0.5SH(99)                             | No                      |
| 12              | 580-1330-0-10                  | FH33J-40S-0.5SH(10)                             | No                      |
| 13              | 580-1330-0-10                  | FH33J-40S-0.5SH(99)                             | No                      |
| 14              | 580-0334-5-05                  | FH29BJ-90S-0.2SHW(05)                           | No                      |
| 15              | 580-0327-0-05                  | FH29BJ-70S-0.2SHW(05)                           | No                      |
| 16              | 580-0327-0-99                  | FH29BJ-70S-0.2SHW(99)                           | No                      |
| 17              | 580-0329-5-05                  | FH29BJ-80S-0.2SHW(05)                           | No                      |
| 18              | 580-0328-2-05                  | FH29BJ-120S-0.2SHW(05)                          | No                      |
| 19              | 580-0326-2-03                  | FH33J-18S-0.5SH(10)                             | No                      |
| 20              | 580-1334-0-99                  | FH33J-18S-0.5SH(99)                             | No                      |
| 21              | 580-0331-7-05                  | FH29BJ-34S-0.2SHW(05)                           | No                      |
| 22              | 580-0331-7-99                  | FH29BJ-34S-0.2SHW(99)                           | No                      |
| 23              | 580-0336-0-05                  | FH29DJ-70S-0.2SHW(05)                           | No                      |
| 24              | +                              | FH29DJ-70S-0.2SHW(99)                           | No                      |
| <u>24</u><br>25 | 580-0336-0-99                  | FH29DJ-70S-0.2SHW(99)                           | No                      |
| 26              | 580-0335-8-05<br>580-0335-8-99 | FH29DJ-100S-0.2SHW(99)                          | No                      |
| 27              |                                | \ /                                             | No                      |
| 28              | 580-0338-6-05                  | FH29DJ-50S-0.2SHW(05)<br>FH29DJ-50S-0.2SHW(99)  | No                      |
| 29              | 580-0338-6-99                  | FH29DJ-60S-0.2SHW(05)                           | No                      |
|                 | 580-0343-6-05<br>580-0343-6-99 | FH29DJ-60S-0.2SHW(99)                           | No                      |
| 30<br>31        |                                | FH29DJ-60S-0.2SHW(99)                           | No                      |
| 32              | 580-0342-3-05                  | 1 7                                             | No                      |
| 33              | 580-0342-3-99                  | FH29DJ-120S-0.2SHW(99)<br>FH29DJ-90S-0.2SHW(05) |                         |
|                 | 580-0340-8-05                  |                                                 | No<br>No                |
| 34              | 580-0340-8-99                  | FH29DJ-90S-0.2SHW(99)                           | No<br>No                |
| 35              | 580-0337-3-05                  | FH29DJ-44S-0.2SHW(05)                           | No                      |
| 36              | 580-0337-3-45                  | FH29DJ-44S-0.2SHW(45)                           | No<br>No                |
| 37              | 580-0339-9-05                  | FH29DJ-110S-0.2SHW(05)                          | No                      |
| 38              | 580-0341-0-05                  | FH29DJ-80S-0.2SHW(05)                           | No                      |
| 39              | 580-0341-0-99                  | FH29DJ-80S-0.2SHW(99)                           | No<br>No                |
| 40              | 580-0341-0-45                  | FH29DJ-80S-0.2SHW(45)                           | No<br>No                |
| 41              | 580-4700-0-99                  | FH65-34S-0.5SH(99)                              | No<br>No                |
| 42              | 580-4700-0-00                  | FH65-34S-0.5SH                                  | No<br>No                |
| 43              | 580-4703-0-00                  | FH65-8S-0.5SH                                   | No<br>No                |
| 44              | 580-4703-0-99                  | FH65-8S-0.5SH(99)                               | No                      |
| 45              | 580-4704-0-00                  | FH65-10S-0.5SH                                  | No                      |
| 46              | 580-4704-0-99                  | FH65-10S-0.5SH(99)                              | No                      |
| 47              | 580-4701-0-00<br>580-4701-0-99 | FH65-15S-0.5SH<br>FH65-15S-0.5SH(99)            | No<br>No                |

| 49 | 580-4708-0-00 | FH65-12S-0.5SH       | No |
|----|---------------|----------------------|----|
| 50 | 580-2448-5-97 | FH26J-55S-0.3SHW(97) | No |
| 51 | 580-2448-5-60 | FH26J-55S-0.3SHW(60) | No |

■ Product list (Custom)
Business430-21027-1\_Regarding DIC PPS compound products that don't reach UL certification rating

| No       | Product code  | Part Number            | UL certification     |
|----------|---------------|------------------------|----------------------|
| 4        | E00 0220 4 00 |                        | status of connectors |
| <u> </u> | 580-0330-4-88 | FH29BJ-60S-0.2SHW(88)  | No                   |
| 2        | 580-0336-0-28 | FH29DJ-70S-0.2SHW(28)  | No                   |
| 3        | 580-0344-0-00 | FH29DJ-70S-0.2SHW(800) | No                   |
| 4        | 580-0335-8-44 | FH29DJ-100S-0.2SHW(44) | No                   |
| 5        | 580-0335-8-17 | FH29DJ-100S-0.2SHW(17) | No                   |
| 6        | 580-0343-6-21 | FH29DJ-60S-0.2SHW(21)  | No                   |
| 7        | 580-0342-3-28 | FH29DJ-120S-0.2SHW(28) | No                   |
| 8        | 580-0342-3-42 | FH29DJ-120S-0.2SHW(42) | No                   |
| 9        | 580-0340-8-21 | FH29DJ-90S-0.2SHW(21)  | No                   |
| 10       | 580-0340-8-42 | FH29DJ-90S-0.2SHW(42)  | No                   |
| 11       | 580-0339-9-21 | FH29DJ-110S-0.2SHW(21) | No                   |
| 12       | 580-0339-9-23 | FH29DJ-110S-0.2SHW(23) | No                   |
| 13       | 580-0341-0-21 | FH29DJ-80S-0.2SHW(21)  | No                   |
| 14       | 580-4703-0-50 | FH65-8S-0.5SH(50)      | Yes                  |
| 15       | 580-4704-0-50 | FH65-10S-0.5SH(50)     | Yes                  |
| 16       | 580-4701-0-50 | FH65-15S-0.5SH(50)     | Yes                  |
| 17       | 580-1333-8-40 | FH33MPJ-42S-0.4SH(40)  | No                   |