Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200								
PRODUCT DISCONTINUANCE NOTICE (PDN)								
PDN #:	M-12-01			for Submission of Order:	28-Feb-2014			
Issue Date:	28-Feb-2013		Last Eligible	Ship Date:	28-May-2014			
Title: M Phone #: 4 Fax #: 4	Paul Barton Marketing Manager - 408-284-8306 408-360-1748 paul.barton@idt.cor							
PRODUCT(S) (List Replacement) AFFECTED: ent Part #(s), if any)	hment I will be discontin	ATTACHM	ENT Yes	□ No			
 Replace slov Obsolete Fa Obsolete As 	R DISCONTINUAN ower speed with faster ab Technology / Proce ssembly Technology / ackage / Material larket	r speed offerings cess	Other:					
 CUSTOMER NOTIFICATION: As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information. Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing. <i>If you have any questions, please feel free to contact your local IDT distributor or sales representative.</i> 								
Customer:			E-Mail Addres	SS:				
Name/Date:			Phone	e#:				
Title:			Fax	x# :				
CUSTOMER	COMMENTS:							
	WLEDGEMENT:							
Received By:			Date:					

-	
IDT FRA-2265-0	l (Rev.02) 04/24/08



Integrated Device Technology, Inc. 6024 Silver Creek Valley Road, San Jose, CA 95138 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: M-12-01

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
74ALVCF162835APA	74ALVCF162835APAG		
74ALVCF162835APF	74ALVCF162835APAG		
74ALVCF162835APFG	74ALVCF162835APAG		
74SSTU32866BBFG	74SSTUBF32866BBFG		
74SSTUAE32866ABFG	74SSTUBF32866BBFG		
74SSTV16859APA	SSTVA16859CGLF		
93V847AGLF	95V847AGLF		
95V157AG	95V157AGLF		
95V2F857AGLF	NONE		
95V2F857AHLF	NONE		
95V847AG	95V847AGLF		
95V857AG	95V857AGLF		
95V857AGI	95V857AGILF		
95V857AH	95V857AHLF		
95V857ALLF	95V857AGLF		
95V857CGLF	CSPT857CPAG		
95V857CHLF	CSPT857CBVG		
97U870AKI	97U870AKLF		
98ULPA877AH	98ULPA877AHLF		
98ULPA877AHI	98ULPA877AHILF		
98ULPA877AK	98ULPA877AKLF		
CSP2510DPG	CSP2510DPGG		
CSP2510DPGI	CSP2510DPGGI		
CSPUA877BVG	CSPUA877ABVG		
SSTUAF32866CHLF	74SSTUBF32866BBFG		
SSTUB32872AHLF	NONE		
SSTUB32872AHMLF	NONE		
SSTVA16859AKLF	SSTVA16859CKLF		
SSTVA32852AHLF	NONE		
		-	
	1		
	1		
	1		
	1		
	1		
<u> </u>	+		