Marketing Bulletin

June 19, 2018

MB – 282

JAE Electronics, Inc. • 142 Technology Drive #100 Irvine, CA 92618 • Ph. (949) 753-2600 • Fax (949) 753-4706 • www.jae.com

D-Sub Series Location Change Notice

Manufacturing of select D-sub series connectors will be changing from JAE Philippines to JAE Wuxi, China in order to utilize available production facility capacity and man-power to maintain on-going long-term production.

1. Production Location Change

Pre-change Production Location JAE Philippines

→

Post-change Production Location JAE Wuxi (China)

2. Production Change Schedule

The location change began with lots shipped during December, 2017. During the running production location change JAE has diligently maintain records of production documentation to avoid mixing production lots.

Due to the transfer of production equipment during the change, products may be pre-produced and stored to not affect customer required delivery.

3. Affected Parts

Please refer to the list below:

	Part no.	Drawing no.	
1	DEU-9PF-F0		
2	DAU-15PF-F0		
3	DBU-25PF-F0	SJ018091	
4	DCU-37PF-F0		
5	DDU-50PF-F0		
6	DEU-9SF-F0		
7	DAU-15SF-F0		
8	DBU-25SF-F0	SJ018092	
9	DCU-37SF-F0		
10	DDU-50SF-F0		
11	DE-9PF-N		
12	DA-15PF-N		
13	DB-25PF-N	SJ018093	
14	DC-37PF-N		
15	DD-50PF-N		
16	DE-9SF-N	C1019004	
17	DA-15SF-N	SJ018094	

18	DB-25SF-N		
19	DC-37SF-N		
20	DD-50SF-N		
21	DESP-JB9PF		
22	DASP-JB15PF		
23	DBSP-JB25PF	SJ018095	
24	DCSP-JB37PF		
25	DESP-JB9SF		
26	DASP-JB15SF		
27	DBSP-JB25SF	SJ018096	
28	DCSP-JB37SF		
29	DE-9PF-T-N		
30	DE-9SF-T-N	SJ018622	
31	DA-15PF-T-N		
32	DA-15SF-T-N		
33	DB-25PF-T-N		
34	DB-25SF-T-N		
35	DC-37PF-T-N	SJ018622	
36	DC-37SF-T-N		
37	DD-50PF-T-N		
38	DD-50SF-T-N		
39	DE-9PR		
40	DE-9SR		
41	DA-15PR		
42	DA-15SR		
43	DB-25PR	C1101720	
44	DB-25SR	SJ101738	
45	DC-37PR		
46	DC-37SR		
47	DD-50PR		
48	DD-50SR		
49	DE-9P-T-NR		
50	DE-9S-T-NR		
51	DA-15P-T-NR		
52	DA-15S-T-NR		
53	DB-25P-T-NR	61102050	
54	DB-25S-T-NR	SJ103058	
55	DC-37P-T-NR		
56	DC-37S-T-NR		
57	DD-50P-T-NR		
58	DD-50S-T-NR		
59		SJ103075	

60	DE-9S-NR	
61	DA-15P-NR	SJ103075
62	DA-15S-NR	
63	DB-25P-NR	
64	DB-25S-NR	
65	DC-37P-NR	
66	DC-37S-NR	
67	DD-50P-NR	
68	DD-50S-NR	
69	DEU-9P-FOR	SJ103082
70	DEU-9S-F0R	
71	DAU-15P-FOR	
72	DAU-15S-FOR	
73	DBU-25P-F0R	
74	DBU-25S-FOR	
75	DCU-37P-F0R	
76	DCU-37S-F0R	
77	DDU-50P-F0R	
78	DDU-50S-F0R	
79	DESP-JB9PR	
80	DESP-JB9SR	614 0 2 0 2 0
81	DASP-JB15PR	
82	DASP-JB15SR	
83	DBSP-JB25PR	SJ103090
84	DBSP-JB25SR]
85	DCSP-JB37PR	
86	DCSP-JB37SR	
87	DBC-25S-F0R	SJ101806

For existing customers who require any special documentation concerning this location change, please contact your JAE account representative by the end of June.

If you have any questions regarding this matter, please contact your JAE account manager.

Thank you for your cooperation.

