

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

PRODUCT DISCONTINUANCE NOTICE

Notice Type Maxim Part Number Recommeded Replacement Last Order Date **Last Delivery Date** Reason N/A Discontinuance MAX16930AGLS/VY+T 19-Jul-2018 19-Jul-2018 The part was not released MAX20040ATPA/VY+ Discontinuance MAX20040ATPA/V+ 19-Jul-2018 19-Jul-2018 The part was not released Discontinuance MAX3110ECWI+G36 N/A 19-Dec-2018 18-Jan-2020 Part can no longer be manufactured Discontinuance MAX3110ECWI+TG36 N/A 19-Dec-2018 18-Jan-2020 Part can no longer be manufactured Discontinuance MAX3110EEWI+G36 N/A 19-Dec-2018 18-Jan-2020 Part can no longer be manufactured MAX3110EEWI+TG36 N/A 19-Dec-2018 18-Jan-2020 Discontinuance Part can no longer be manufactured Discontinuance MAX3111ECWI+G36 N/A 19-Dec-2018 18-Jan-2020 Part can no longer be manufactured Discontinuance MAX3111ECWI+TG36 N/A 19-Dec-2018 18-Jan-2020 Part can no longer be manufactured MAX3111EEWI+G36 N/A Discontinuance 19-Dec-2018 18-Jan-2020 Part can no longer be manufactured Discontinuance MAX3111EEWI+TG36 N/A 19-Dec-2018 18-Jan-2020 Part can no longer be manufactured MAX34461ETM+ MAX34461AA00+ Discontinuance 19-Jul-2019 18-Jan-2020 Part can no longer be manufactured Discontinuance N/A MAX3710EVKIT# 19-Jul-2018 19-Jul-2018 EVKIT is No Longer Supported MAX514ACWI+ Discontinuance N/A 19-Jul-2019 18-Jan-2020 Part can no longer be manufactured MAX514AEWI+ N/A Discontinuance 19-Jul-2019 18-Jan-2020 Part can no longer be manufactured Discontinuance MAX514BCWI+ N/A 19-Jul-2019 18-Jan-2020 Part can no longer be manufactured Discontinuance MAX514BEWI+ N/A 19-Jul-2019 18-Jan-2020 Part can no longer be manufactured Discontinuance MAX9875EVKIT+ N/A 19-Jul-2018 19-Jul-2018 EVKIT is No Longer Supported MX7538KCWG+ N/A Discontinuance 19-Jul-2019 18-Jan-2020 Part can no longer be manufactured Discontinuance PHY1095-01DS+GR1 N/A 19-Jul-2018 19-Jul-2018 The part was not released

PDN #: M000871

DATE: 19-Jul-2018