

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000970

DATE: 26-Jul-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS2703G+T&R	N/A			Part reactivated from prior notice: M000962I
Reactivation	DS28EL15X+U	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX16092UK28BGA+T	N/A			Part reactivated from prior notice: M000969
Reactivation	MAX4461TETT+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX5860DUXH+	N/A			Part reactivated from prior notice: M000969
Reactivation	MAX5860PUXH+	N/A			Part reactivated from prior notice: M000969
Reactivation	MAX6070AAUT41+	N/A			Part reactivated from prior notice: M000969I
Reactivation	MAX6389LT31D3+	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX6466XR18+	N/A			Part reactivated from prior notice: M000962I
Reactivation	MAX6466XR18+T	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX8891EXK15+T	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX8973AEWI+	N/A			Part reactivated from prior notice: M000965I
Discontinuance	806-0671-83	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	DS4100H+	N/A	26-Oct-2019	24-Jan-2021	Part can no longer be manufactured
Discontinuance	DS4100HW+	N/A	26-Oct-2019	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16907RATE/V+CMF	MAX16907RATE/V+	24-Jan-2021	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1707EVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX17582GTM+	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1786AEUI+TGH8	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX20030ATMD/V+	MAX20030BATMD/V+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20307EWL+	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX20329EWL+	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX20329EWL+T	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2687EVKIT#	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX2687EVKIT+	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX2741EVKIT	MAX2769EVKIT+	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported

Discontinuance	MAX8561EVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX86900AEFD+T	MAX86906EFD+T	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX86907BEFD+T	MAX86907BEFD+TCQD	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX881REVKIT	MAX881REVKIT#	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX9382EVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX96911DGTJ/VY+W	MAX96911DGTJ/VY+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96911DGTJY+E2	MAX96911DGTJ/VY+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96911GGTJY+E2	MAX96911GGTJ/VY+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96912EGTMY+E2	MAX96912EGTM/VY+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAXQ2000-RBX+	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAXREFDES100HDK#	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	VT1157SAFQR	VT1157SAFQX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1317SFCR-001	VT1317SFCX-001	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1334SFCR	VT1334SFCX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1527MBFQX-008	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1677SBFQX-008	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	VT267AWFQX-ADJ-008	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	VT356FCR-ADJ-007	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	VT382BFCR-ADJ-001	VT382BFCX-ADJ	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured