

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000989I

DATE: 11-Apr-2020

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DG200AAK	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	DG403AK	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	DG409AK	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	DG419AK	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	DG509AAK	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	DS21348GN	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	DS34S108GN	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	DS34T104GN	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX1211ETL+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX13430ETB+	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX1452C/DW	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX1912EUB+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX3265CUE+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX358MJE	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX382CWN+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX384CWN+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX385ESE+T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX4647EUT	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX4648EUT-T	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX4737EBE	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured
Discontinuance	MAX5894EGK+TD	N/A	11-Apr-2020	11-Apr-2020	Part can no longer be manufactured