

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE. CA 95134

PRODUCT DISCONTINUANCE NOTICE

Maxim Part Number Recommeded Replacement Last Order Date **Last Delivery Date Notice Type** Reason N/A Discontinuance 77053022A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG308ACJ+ Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG381ACJ+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG381ACWE+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG381ACWE+T N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG390AAK N/A 27-Mar-2023 Discontinuance 28-Sep-2022 Part can no longer be manufactured DG390ACJ+ Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG390ACWE+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG390ACWE+T Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG409C/D N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG413C/D Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG419C/D Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG423DJ+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG506AC/W+ Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG507AC/D N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG507AC/W+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG507C/W+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG508AC/D Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG509C/W+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DG528DN+ N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured DG528DN+T Discontinuance N/A 28-Sep-2022 27-Mar-2023 Part can no longer be manufactured Discontinuance DS1856B-020+ N/A 21-Sep-2022 20-Mar-2023 Part can no longer be manufactured N/A Discontinuance DS1856B-020+T&R 21-Sep-2022 20-Mar-2023 Part can no longer be manufactured Discontinuance DS1859B-050+T&R/B N/A 21-Sep-2022 20-Mar-2023 Part can no longer be manufactured Discontinuance DS28E02Q-W01+2T N/A 21-Sep-2021 20-Mar-2022 Part can no longer be manufactured DS4830T+T

21-Sep-2022

20-Mar-2023

PDN #: M001042

DATE: 21-Sep-2021

Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-Oct-2021

N/A

Discontinuance

Discontinuance	HI1-0201HS/883B	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	IH5341EWE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX1245AEPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX1245BCPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX1245BEPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX147ACPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX147BEPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX148ACPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX148BCPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX24011E/D+	N/A	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX319C/D	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX3265CUB+T	N/A	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX3265CUE+	N/A	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX3286CTI+	N/A	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX3286CTI+T	N/A	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX366C/D	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX368CPN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX368CWN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX368CWN+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX368EPN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX368EWN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX368EWN+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX369CPN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX369EWN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX369EWN+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX3765CUB+	N/A	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX3765CUB+T	N/A	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX378MLP	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX378MLP/883B	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX388CPN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX388CWG+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX388CWG+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX388EPN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX389CWG+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX389CWG+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX389EPN+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured

Discontinuance	MAX389EWG+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX389EWG+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4391EPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4391ESA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX452CSA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX452CSA+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX452ESA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX452ESA+T	N/A	21-Sep-2021	21-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX4531CWP+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4532EAP+T	N/A	21-Sep-2021	21-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX453CPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX453CSA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX453CSA+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4540EAP+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX454CPD+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX455CPP+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured
Discontinuance	MAX4578CAP+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4598CWP+T	N/A	21-Sep-2021	21-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX4613C/D	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4631ESE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4631ESE+T	N/A	21-Sep-2021	21-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX4633CSE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX4633CSE+T	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX5003CSE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX5003ESE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX634CPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX634CSA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX634EPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX634ESA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX638ACPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX638ACSA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX638AESA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX638AMJA	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX722ESE/G0F+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX732CWE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX732EPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured

Discontinuance	MAX732EWE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX752CPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX752CWE+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAX752EPA+	N/A	28-Sep-2022	27-Mar-2023	Part can no longer be manufactured
Discontinuance	MAXQ1062ETP+T	MAXQ1061ETP+T	21-Sep-2022	20-Mar-2023	Part can no longer be manufactured
Discontinuance	MX7528JN+2	N/A	23-Mar-2022	23-Mar-2022	Part can no longer be manufactured
Discontinuance	MX7528JN+4	N/A	23-Mar-2022	23-Mar-2022	Part can no longer be manufactured
Discontinuance	MX7528LN+	N/A	23-Mar-2022	19-Sep-2022	Part can no longer be manufactured