

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M001077I

DATE: 27-Jun-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DG417CJ+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	DG418CJ+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	DS1250AB-100+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	DS1810R-5-U+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	DS2198GN	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	IH5040CWE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	IH5040CWE+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX11614EVSYS+	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX14746EWA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX14746EWA+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX14987EXP+CKR	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX14987EXP+TCKR	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX15090EVKIT#	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX156BCWI+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX1652EEE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX1652EEE+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX1687EUE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX1687EUE+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX16930ATLR/V+CM7	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX16933BATIS/V+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX16933BATIS/V+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX16975BAEE+CFY	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX16975BAEE+TCFY	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX17039EVKIT+	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX1734EUK15+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX1734EUK15+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured

Discontinuones	MAX1922ETB+	N/A	27-Jun-2022	27 Dog 2022	Part can no langer he manufactured
Discontinuance				27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX1922ETB+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX19586ETN+D	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX20066EVKIT#	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX20413ATGC/V+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX20413ATGC/V+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX2473EUT+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX2473EUT+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX2902EVKIT#	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX317EPA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX3205EAWL+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX3205EAWL+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX361CPE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX366CPA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX40004ANS12+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX40004ANS12+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX44299EVKIT#	N/A	27-Jun-2022	27-Jun-2022	EVKIT is No Longer Supported
Discontinuance	MAX4507CAP+	N/A	30-Dec-2022	29-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX4507CAP+T	N/A	30-Dec-2022	29-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX4526CPA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4543ESA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4543ESA+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4664CPE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4700CWE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4700CWE+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4752EGE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4752EGE+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX4936AEVKIT#	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX5879EVKIT#	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX5974EEVKIT#	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX6326XR25+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6326XR25+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6347XR46+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6347XR46+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6358SVUT+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6358SVUT+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured

Discontinuoses	MAY6250DVIII.	N/A	27 Jun 2022	27 Dec 2022	Dort can no languar ha manufactured
Discontinuance	MAX6359RVUT+		27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6359RVUT+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6376XR22+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6376XR22+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6376XR26+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6376XR26+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6378XR44+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6378XR44+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6380UR37+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6380UR37+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6383XR29D1+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6383XR29D1+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6384XS26D3+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6384XS26D3+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6386XS46D2+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6386XS46D2+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6394US470D1+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6394US470D1+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6466UR23+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6466UR23+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6467XS32D3+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6467XS32D3+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6467XS32D3/V+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6467XS32D3/V+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6712LEXS+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6712LEXS+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6721UTSVD3+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6721UTSVD3+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6856UK16D5+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX6856UK16D5+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX704EPA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX7324EVKIT+	N/A	27-Jun-2022	27-Dec-2023	EVKIT is No Longer Supported
Discontinuance	MAX748AEPA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX77277CEWB+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX77277CEWB+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance	MAX792TEPE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured

Discontinuance MAX819MCSA+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX819MCSA+T N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX8662ETM+TGH7 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9646EBS+CK0 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9646EBS+TCK0 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MX574AJEPI+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MX5733JEWE+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured						
Discontinuance MAX8662ETM+TGH7 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9646EBS+CK0 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9646EBS+TCK0 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+T N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+T N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MX574AJEPI+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured	Discontinuance	MAX819MCSA+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance MAX9646EBS+CK0 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9646EBS+TCK0 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+T N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MX574AJEPI+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured	Discontinuance	MAX819MCSA+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance MAX9646EBS+TCK0 N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+T N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MX574AJEPI+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured	Discontinuance	MAX8662ETM+TGH7	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance MAX9877AERP+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MAX9877AERP+T N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MX574AJEPI+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured	Discontinuance	MAX9646EBS+CK0	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance MAX9877AERP+T N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured Discontinuance MX574AJEPI+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured	Discontinuance	MAX9646EBS+TCK0	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance MX574AJEPI+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured	Discontinuance	MAX9877AERP+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
	Discontinuance	MAX9877AERP+T	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
Discontinuance MX7533JEWE+ N/A 27-Jun-2022 27-Dec-2023 Part can no longer be manufactured	Discontinuance	MX574AJEPI+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured
	Discontinuance	MX7533JEWE+	N/A	27-Jun-2022	27-Dec-2023	Part can no longer be manufactured