

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

PRODUCT DISCONTINUANCE NOTICE

Notice Type Maxim Part Number Recommeded Replacement Last Order Date **Last Delivery Date** Reason DS28E40G/V+T N/A 02-May-2023 29-Oct-2023 Discontinuance Part can no longer be manufactured N/A Discontinuance MAX1098CEAE+T 02-May-2023 29-Oct-2023 Part can no longer be manufactured Discontinuance MAX1099CEAE+T N/A 02-May-2023 29-Oct-2023 Part can no longer be manufactured Discontinuance MAX1298CEAE+T N/A 02-May-2023 29-Oct-2023 Part can no longer be manufactured Discontinuance N/A MAX1299CEAE+T 02-May-2023 29-Oct-2023 Part can no longer be manufactured MAX20480DB/VY+CTF MAX20480DATEB/VY+ 29-Oct-2023 Discontinuance 02-May-2023 The part was not released Discontinuance MAX20480DC/VY+CTF MAX20480DATEC/VY+ 02-May-2023 29-Oct-2023 The part was not released Discontinuance MAX20480DD/VY+CTF MAX20480DATED/VY+ 02-May-2023 29-Oct-2023 The part was not released MAX20480DI/VY+CTJ MAX20480DATEI/VY+ 29-Oct-2023 The part was not released Discontinuance 02-May-2023 Discontinuance MAX5035BUPA+T N/A 02-May-2023 29-Oct-2023 Part can no longer be manufactured MAX5156BCPE+ N/A Discontinuance 02-May-2023 29-Oct-2023 Part can no longer be manufactured Discontinuance N/A MAX515EPA+ 02-May-2023 29-Oct-2023 Part can no longer be manufactured Discontinuance MAX547ACQH+TD N/A 02-May-2023 29-Oct-2023 Part can no longer be manufactured N/A Discontinuance MAX547BEQH+ 02-May-2023 29-Oct-2023 Part can no longer be manufactured Discontinuance MAX6304CPA+ N/A 02-May-2023 29-Oct-2023 Part can no longer be manufactured MAX6304EPA+ Discontinuance N/A 02-May-2023 29-Oct-2023 Part can no longer be manufactured Discontinuance N/A TMC262-EVAL 25-Apr-2022 25-Apr-2022 Part can no longer be manufactured TMC429+TMC26X-EVAL N/A Discontinuance 25-Apr-2022 25-Apr-2022 The eval kit is no longer supported TMC457-EVAL N/A Discontinuance 25-Apr-2022 25-Apr-2022 Part can no longer be manufactured

PDN #: M001074I

DATE: 25-Apr-2022