

## **Global Change Notification (GCN)**

Product Family Impact 10619597

**GCN Number** 

Series 76285;76286;76855;76856;76985;76986;171886

December 06, 2013

Date Issued


Reason For Change

**Product Component Change** 


Change Description

This purpose of this letter is to inform you that the change of increased lead in, long jog terminals, and added plastic for improved pin retention and true position. Series numbers affected by this change are

76285;76286;76855;76856;76985;76986;171886. Note: Rev 3 application tools will work on Rev 1 and Rev 2 product. Rev 1 and Rev 2 tools will "NOT" work on proposed product design which is subject of change notification. Reference QN #10529280



increased lead-in, long jog terminals



Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception 8D Corrective Action Changes Assessment Of Change samples available upon request (How Product Will Be Qualified & Validated) Internal Molex Qualification Date October 31, 2013 (Planned Date Information Available) Sample Availability Date October 31, 2013 (Changed Part) Date of Implementation January 03, 2014 Method of Identifying Change Running Change - 01/03/2014 to start - date code identifier Recommended Replacement Parts

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com