

Global Change Notification (GCN)

Product Family	1.25 FFC ZIF HSG ASSY	10648927		
		GCN Number		
Series	5597	December 09, 2014		
		Date Issued		
Reason For Change	Supplier Changes To Raw Material			
Change Description	This is to inform you of molding resin change for actuator 5571series. The material changes from VALOX420SE0-1001 to DURANEX3216-EF2001. Finished Goods are 5597series (1.25 FFC ZIF HSG ASSY), assembled in our vendor, Aidex. The current resin is being produced at SABIC. This time Molex will purchase new resin from WINTECH POLYMERS as a stable material source for our future manufacturing activities. Mass production starting date is estimated as 30th Jan, 2015 (Can be changeable due to demand and manufacturing situation of 5597series). The affected items are as follows · · · 39532034, 39532035, 39532044, 39532045, 39532054, 39532055, 39532064, 39532065, 39532074, 39532075, 39532084, 39532085, 39532094, 39532095, 39532104, 39532105, 39532114, 39532115, 39532117, 39532124, 39532125, 39532134, 39532135, 39532144, 39532155, 39532164, 39532165, 39532174, 39532177, 39532184, 39532185, 39532194, 39532195, 39532204, 39532205, 39532214, 39532215, 39532224, 39532225, 39532234, 39532235, 39532244, 39532255, 39532234, 39532235, 39532244, 39532275, 39532284, 39532285, 39532294, 39532295, 39532304, 39532305, 39532314, 39532315, 39532324, 39532235, 39532344, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532355, 39532344, 39532355, 39532344, 39532355, 39532344, 39532355, 39532344, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532354, 39532355, 39532344, 39532355, 39532354, 3953235			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-	mail message.		
Reason For Short Notice Exception	Medical Industry			
Assessment Of Change (How Product Will Be Qualified & Validated)	First Article Inspection was conducted to find no quany significant influence on products' performance.	uality issues. There will not be		
Internal Molex Qualification Date (Planned Date Information Available)	July 31, 2014			
Sample Availability Date (Changed Part)	December 15, 2014			
Date of Implementation	January 30, 2015			
Method of Identifying Change	Lot Number			
Recommended Replacement Parts	Not Applicable			
Last Time Buy Date for Obsolete Parts				
Last Time Ship Date for Obsolete Parts				

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com