

Product Family	MX150		106	50324	
	L		GCN	Number	
Series	various		August	August 27, 2014	
			Date	e Issued	
Reason For Change	New, Modified, (Or Replacement Tooling			
Change Description	This letter is to inform you that capacity tools are being fabricated to support increased demand. Please see table below for affected series numbers and implementation dates. This is strictly capacity tooling with no design or material changes.				
- CP4 /2	S	Series	Component(s)	Date of implementation	
N TONG		34770	TPA	11/23/2014	
GROMET SEAL	-35252	33471-04**, 34770	Grommet Cap	12/17/2014	
			Housing		
		33472-06**, 33472-07**	Grommet Cap TPA	11/29/2014	
		33482-06**	Grommet Cap TPA	12/29/2014	
34470	-	33482-08**	Housing	11/4/2014	
	e-33471 & 33472	34675	Housing	12/23/2014	
Part Numbers Affected	Please refer to (CustomerPartList.csv attac	ched to e-mail mess	age.	
Reason For Short Notice Exception	New Capacity				
Assessment Of Change	validation testing				
(How Product Will Be Qualified & Validated)					
Internal Molex Qualification Date (Planned Date Information Available)	December 29, 2014				
Sample Availability Date (Changed Part)	December 29, 2014				
Date of Implementation	January 01, 2015				
Method of Identifying Change	added cavity numbers				
Recommended Replacement Parts	NA				
Last Time Buy Date for Obsolete Parts					
Last Time Ship Date for Obsolete Parts					

Contact	Name	E-mail	Phone Number		
Sales Engineer	Please refer to e-mail message for your local sales engineer.				
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416		
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751		
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472		
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352		

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com