

## **Global Change Notification (GCN)**

Product Family USB A Plug 10666760

GCN Number

Series 67329 January 20, 2015


Date Issued


Reason For Change

**Product Component Change** 

Change Description

The purpose of this letter is to inform you that we plan to change 67329 USB A Plug plating method from hang plating to reel to reel plating to improve yield in process, the change is targeted to implemented on 2015-02-28. We have done 8h/12h/24h salt spray test for this change and confirmed no impact. the part list is as enclosed.





Part Numbers Affected Plea

Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception

8D Corrective Action Changes

Assessment Of Change (How Product Will Be Qualified & Validated)

8h/12h/24h Salt spray test ok.

Internal Molex Qualification Date (Planned Date Information Available)

December 30, 2014

Sample Availability Date (Changed Part)

December 20, 2014

Date of Implementation

February 28, 2015

Method of Identifying Change

Add :WORD"C"on the label

Recommended Replacement Parts

n/a

Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com