

**Product Family** 

## **Global Change Notification (GCN)**

10679140

Magnetic Jack PoE enabled products

**GCN Number** Series 85731, 85732, 85734, 85735 March 27, 2015 Date Issued Reason For Change Product Component Change Change Description The purpose of this change is to improve assembly reliability of Magnetic Jack product series 85731, 85732 and 85734 by adding two additional latches on the rear shield on the top face of the connector. The change will have no impact on product performance including EMI. 相等外的學來緊急 Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception Assessment Of Change Assembly tests will be conducted to evaluate the connection between rear and (How Product Will Be Qualified & Validated) front shield. Internal Molex Qualification Date September 01, 2015 (Planned Date Information Available) Sample Availability Date September 15, 2015 (Changed Part) Date of Implementation October 01, 2015 Method of Identifying Change The new rear shields will have 2 additional latches on the top face of the connector, see attached pictures Recommended Replacement Parts Last Time Buy Date for Obsolete Parts Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com