

Material

Global Change Notification (GCN)

		Product Family	Loose crimp t	erminals	10682933		
					GCN Number		
		Series	1376, 1377, 3	.973 & 2273	April 28, 2015		
					Date Issued		
		Reason For Change	Change In Pa	ckaging Specifications			
Change Description			This letter is to announce that Molex is changing the packaging quantities for loose terminals series 1376, 1377, 1973 & 2273 to make the parts fit better in the boxes.				
200 - 1903 - 1	-	Current minimum	New box				
Aaterial	Eng Series	order quantity	quantity				
098109	1973	4000	3000				
098104	1973	4000	3000	1			
091123	2273	6000	4000				
092133	1376	6000	4000	1			
092134	1376	6000	4000				
096132	1376	6000	4000				
096134	1376	6000	4000				
096138	1376	6000	4000				
348509	1376	6000	4000				
091134	1377	6000	4000				
095132	1377	6000	4000				
348511	1377	6000	4000				
	Pa	art Numbers Affected	Please refer t	o CustomerPartList.csv atta	ched to e-mail message.		
-							
ŀ	Reason For Si	hort Notice Exception					
(How Pro	As duct Will Be (ssessment Of Change Qualified & Validated)	Not applicable	3			
(Pla		lex Qualification Date nformation Available)					
	Sar	nple Availability Date (Changed Part)					
	Da	te of Implementation	May 07, 2015				
	Method o	of Identifying Change	New box quar	New box quantities			
	Recommende	ed Replacement Parts	Not Applicable	2			
Last	Time Buy Da	ate for Obsolete Parts					
Last	Time Ship Da	ate for Obsolete Parts					

Contact	Name	E-mail	Phone Number		
Sales Engineer	Please refer to e-mail message for your local sales engineer.				
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416		
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751		
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271		
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352		

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com