

## **Global Change Notification (GCN)**

of innovation			
Product Family	Shielded Top Entry Jacks	10686563	
		GCN Number	
Series	36743, 36756, 85508, 95623, 120341, 120465	May 22, 2015	
		Date Issued	
Reason For Change	Product Component Change		
Change Description	This is to inform you that Molex is removing the shield flap from the above product series Jack recess. The purpose of this is to ensure plugs can not get stuck in the Jack recess. This modification does not affect the function of the part mechanically or electronically.		
The state of the s			

Before the removal of the Shield flap After the removal of the Shield flap Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception 8D Corrective Action Changes Assessment Of Change This change has no effect on the function of the part mechanically or electronically (How Product Will Be Qualified & Validated) Internal Molex Qualification Date May 11, 2015 (Planned Date Information Available) Sample Availability Date May 13, 2015 (Changed Part) Date of Implementation May 29, 2015 Method of Identifying Change On the initial shipments, there will be a label on the boxes Recommended Replacement Parts Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number	
Sales Engineer	Please refer to e-mail message for your local sales engineer.			
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416	
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751	
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271	
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352	

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com