

Product Cha	ange Notificatio	n	1	0512887	
Date August					
Part Numbers Affe	ected:	See Next Page			
Product Description	on:	Changing selected Mini-Fit and KK® Product that wer Overall Gold Plated Termin to Select Gold, or Gold on the contact area, and Matt in solder tail area (changin solder tails from Overall G Plating to Matte Tin Plating	e nals ly in e Tin g old		
Product Image: Mini-Fit®			The second second		
KK®		//////////////////////////////////////			
	Overall Gold plat removed from so tail area only and replaced with Ma Tin plating	IderContact area to have sameamount of Gold Plating; no			
	Part numbers to				

	will be a running nge		
Change Effective Date:	Nov 1st, 2011		
For further information ple	ase contact your local Molex sales representative.		
This will be a running cha	te: old plating from the solder tail area but plating will remain the same in the contact area. nge, so the part numbers will remain the same and parts shipped after Nov 1st, 2011 will transition to		

remain the same;

This change will remove gold plating from the solder tail area but plating will remain the same in the contact area. This will be a running change, so the part numbers will remain the same and parts shipped after Nov 1st, 2011 will transition to the select gold plating in the contact area and matte tin in the tail area. All product shipping through Oct. 31st, 2011 will have continue to have overall gold on the header pin. Beginning November 1st, 2011, all parts on the attached list will transition to gold plating in the contact area and matte tin in the solder tail area.

Molex, Inc.

2222 Wellington Court Lisle, Il 60532 TEL: 630-969-4747 FAX: 630-

www.molex.com