




Product Change Notification (PCN)

PCN Number	501466	Date Issued	June 01, 2017
Reason for Change	Supplier Change		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Assessment of Change	First article inspection		
Internal Molex Qualification Date	February 17, 2017		
Sample Availability Date (Changed Part)	February 17, 2017		
Planned Implementation Date	June 19, 2017		
Method of Identifying Change	Date code		

Before Change



After Change

Change supplier for component part numbers 380021158, 380021444, 380021449, 380021131, 380021134, 380021136, 380021141, 380021149, 380021152, 380021161, 380021383, 380021385, 380021432, 380021437, 380021453, 380021454, 380021456, 380021475, 380021476.
 Please see attached impacted parts list.
 Fit Form or Function is not affected.

RFI RELEASED



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501466**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

386107803
386608802
386608803
386608804
386608805
386608806
387390569
387590374
387590374
387600104
387600106
387600108
387600110
387600118
387600302
387600303
387600303
387600304
387600308
387600315
387700102
387700103
387700104
387700105
387700106
387700108
387700109
387700110
387700111
387700112
387700113
387700116
387700124
387700305
387700320
387790238
387800103
387800104
387800106
387800110
387800120