

505167

PCN Number

12/11/2017

Creation Date

Change Management Worksheet

Initiator/Change Advocate **Kim, Won-Sick**

Product Family **HSAUTOLINK R/A HEADER EMBOSS TAPE**

Series **104087/104223 / 49616**

RPM Number

Change Description
(Visible to Molex internal
only)

Design of the packing(Emboss pocket) will be changed to prevent bent pin. Only packing(Emboss pocket) design will be changed. (No impact on product quality)


Reason for short notice exception **SR - Special Request**

Reason for Change **PCQC - Packaging Method/Quantity Changing**

Target run-in Date **2/9/2017**

Insert pictures below. Adding information to clarify the change.
(Text in the photo's is the only free text format area on the CFD)

Photos



(text)

(text)

**List of part numbers to
be run in the IAR**

496160301
1040870801
1040870805
1040870817
1040870901
1040870911
1040870915
1040870916
1040870917
1040870924
1040870951
1042230301
1042230901
1042230905
1042230911
1042230917
1042230924
1042230935