



# Product Change Notification (PCN)

PCN Number	509428	Date Issued	March 19, 2021
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Plant Closure		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	May 21, 2021		
Sample Availability Date (Changed Part)	May 21, 2021		
Planned Implementation Date	June 30, 2021		
Method of Identifying Change	Date code		

RELEASED

## Before Change

### Overview

- The purpose of this letter is to change plating chemical from PdNi with gold flash to Gold for Picoflex series terminal because of the Picoflex range transfer to Malaysia due to the Shannon closure and the lack of a localised plating house that can plate PdNi.

## After Change

### Overview

- Full product testing has been completed and change has no impact on the performance of the product. The PdNi gold flash and gold-plated parts can be mated together without impacting product performance.
- Molex Malaysia Part Number(s) Affected:
  - Please see the part list attached.
- The qualification report is available once requested.
- Drawing will be revised according to this change.





## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509428**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

PCN #	Molex Part #
509428	903273304
509428	903273306
509428	903273308
509428	903273310
509428	903273320
509428	903273324

**Part numbers affected:**

90327-3312
90327-3314
90327-3316
90327-3318
90327-3326