

## **Product Change Notification (PCN)**

PCN Number	510757	Date Issued	November 23, 2021
Reason for Change	Change Supplier		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Reason for Short Notice	Force Majeure		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	November 26, 2021		
Sample Availability Date (Changed Part)	November 26, 2021		
Planned Implementation Date	December 07, 2021		
Method of Identifying Change Product made after planned implementation date can contain the change After Change			
Before Change	Alter C	nange	
<ul> <li>Potting is used to provide a seal between the insert and shell on the back half of the receptacle assembly. The standard potting is black in color (left image). The alternate is blue (right image).</li> </ul>		₩ dPower receptacles, plus select № nporarily change from using a blac mpound	
With a set of the set	— T — T — If • Part N — S	t Impact he blue potting compound is sligh here is no impact to fit, form or fui '267 rating remains umber Impact teries 130066 and 130067, plus so ttached spreadsheet.	nction.

## **molex**<sup>®</sup>

**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510757**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PCN #	Molex Part #	
510757	386390067	
510757	1201110001	
510757	1300660050	
510757	1300660054	
510757	1300660090	
510757	1300660111	
510757	1300660152	
510757	1300660154	
510757	1300660326	
510757	1302990100	
510757	1302990200	