Attn:

DIGI-KEY

SUBJECT: Notice of Marking appearance change of Chip Common Mode Choke Coil (DLW5B series)

Dear Sir and Madam,

Thank you very much for your patronage on our products.

We would like to inform you that we will change the "Marking appearance" of our Chip Common Mode Choke Coil (DLW5B series). Please refer to the details below.

1. Applicable Products

Chip Common Mode Choke Coil: DLW5BS series, DLW5BT series Please refer to "Appendix 1".

The listed Part Number(s) in Appendix 1 is based on order history within three years and is either registered in our EDP system or where we have customer specification approval.

2. Reason of change

The current "Ink-Marking" type has capacity/cost issues, and we are unable to expand production capacity. In order to expand production capacity of Marking type, we will change the marking method to "Laser-Marking".

3. Contents of change

	Current	After change
Marking method	Ink-Marking	Laser-Marking
Murata Part NO		

* Please refer to "Appendix 2" for detail of marking appearance.

* Electrical characteristic is exactly the same as current product.

4. Schedule

Date of Shipment for the new type: October 1, 2012

5. Request to you

Please feel free to contact us if you have any special inquiry and/or questions. If we do not receive any reply or requests from you by the end of Sep., 2012, we will regard it as being accepted and we will proceed with this change.

Thank you in advance for your cooperation and understanding in this matter.

Yours faithfully,

K. Utrumi

K.Utsumi/Manager Business Development Support Sec. II Planning & Market Promotion Dept. Murata Manufacturing Co., Ltd.



Appendix 1

< PART NO. LIST >

CUSTOMER PART NO.	MURATA PART NO. (Current Type)	MURATA PART NO. (New Type)
014692	DLW5BSN102SQ2L	DLW5BSM102SQ2L

<u>DLW5B*series</u> マーキング外観比較 DLW5B*series Marking Appearance

