#### **Light is OSRAM**



16.09.2019

# OS-IN-2019-029 Additional Plasma Glazing for OSLON Compact CL/CM Family

Objective	Introduction of an additional Plasma Glazing for OSLON Compact
Products affected	LUW CEUP.CE; LUW CEUN.CE; LCY CEUP; LUW CEUP.HD
Background	The silicon surface of the device can be sticky and can easily contaminated within the supply chain. An additional Plasma Glazing step will be introduced to further reduces stickiness.  There is no change in physical outlines and materials of the affected LEDs.
Realization	Please refer to the customer package for detailed description of the change.
Time Schedule	Changes will be applied starting CW40.
Assessment	No change in fit, form, function and reliability of affected products.

Please direct your inquiry to your local Sales office.

OSRAM Opto Semiconductors GmbH

Head Office:

Leibnizstrasse 4 93055 Regensburg, Germany Phone +49 941 850-5 Fax +49 941 850-1002 www.osram-os.com





Additional Plasma Glazing for OSLON Compact CL/CM Family

**Customer Information Package** 

OS QM CQM A | 16.09.2019

Light is OSRAM







# Additional Plasma Glazing for OSLON Compact CL/CM Family

## Reason of Change

Quality improvement due to reduced stickiness for contamination.


No change in fit, form, function and reliability of affected products.






# Additional Plasma Glazing for OSLON Compact CL/CM Family

#### **Current Process Flow**



#### **Target Process Flow**











# **Additional Plasma Glazing for OSLON Compact CL/CM Family**

# **Affected Products**

## **Product Name**

LUW CEUP.CE

LUW CEUN.CE

LCY CEUP

LUW CEUP.HD







# **Additional Plasma Glazing for OSLON Compact CL/CM Family**

# **Time Schedule**

Changes will be applied starting CW40.





# Thank you.

