



NO: DATE: December 6, 2017 **PRODUCT**:F3UV-XW, F3UV-H, F32, F39-FU1M**TYPE**:Product Discontinuation

F3UV-XW series, F3UV-H series, F32 series and F39-FU1M UV Power Monitor will be Discontinued; No Recommended Replacement

Discontinuation date: February 2018

Note: Date is subject to change based on raw materials and components availability at the factory.

Affected Parts

Product discontinuation		Recommended replacement	
Model	Description	Model	Description
F3UV-XW41	UV amplifier unit	No recommended replacement	
F3UV-XW11		No recommended replacement	
F3UV-XW11-1		No recommended replacement	
F3UV-HT	UV head unit	No recommended replacement	
F3UV-HM		No recommended replacement	
F32-70	UV fiber unit	No recommended replacement	
F32-300		No recommended replacement	
F32-300 3M		No recommended replacement	
F32-300 5M		No recommended replacement	
F32-300 10M		No recommended replacement	
F39-FU1M	Accessory	No recommended replacement	

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only major changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.