

PRODUCT DISCONTINUANCE

Generic Copy

31-MAR-2005

SUBJECT: ON Semiconductor Product Discontinuance #13977

TITLE: 1Q05 (1ST QUARTER 2005) Product Discontinuance Notice

LAST BUY DATE: 30-Sep-2005 LAST SHIP DATE: 31-Mar-2006

AFFECTED PRODUCT DIVISION:

Discretes Products Analog Products Logic Products ECL Products Power Products

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact Sales Office or Mark Wasilewski <RYGF20@onsemi.com>

NOTIFICATION TYPE:

Customers must notify ON Semiconductor in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source."

ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

DESCRIPTION AND PURPOSE:

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, ON Semiconductor is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. ON Semiconductor continually monitors worldwide sales and billings activities on all the products offered to its customers. The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

ON Semiconductor has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, ON Semiconductor has partnered with Rochester Electronics who will carry any remaining device inventory as well as mask sets, etc. to potentially allow for a continued source after ON Semiconductor has completed its business process.

Issue Date: 31 Mar, 2005 Page 1 of 11

Product Discontinuance #13977

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Mark Wasilewski (email is m.wasilewski@onsemi.com) 602.244.5114 USA

Europe:

Herve Marchionini (email is herve.marchionini@onsemi.com) 33.5.34.61.12.68 or 1.602.244.4170 France

Japan & Asia Pacific: Nobuyuki Otake (email is nobuyuki.otake@onsemi.com) 81.241.27.5460 Japan

NOTE: SUBSEQUENT TO PUBLISHING A DISCONTINUANCE NOTICE, ON SEMICONDUCTOR WILL ALLOW SIX (6) MONTHS FROM THE ANNOUNCEMENT DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS.

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

End of life buy orders must be placed before September 30, 2005 and End of life buy orders must be shipped before March 31, 2006

Issue Date: 31 Mar, 2005 Page 2 of 11

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
1SS383T1G	None	N/A
2C3773WP	None	N/A
2N7008	2N7008	INDUSTRY
2N7008RLRA	2N7008	INDUSTRY
2N7008RLRE	2N7008	INDUSTRY
BUL642D2	None	N/A
CS46054N8	None	N/A
CS5212ED14	None	N/A
CS5212EDR14	None	N/A
CS5212GD14	None	N/A
CS5212GDR14	None	N/A
LSE5384LFBV	None	N/A
MBRM140ET1	None	N/A
MBRM140ET3	None	N/A
MBRM140ET3G	None	N/A
MC44608P100	None	N/A
MC74HC161AD	None	N/A
MC74HC161ADG	None	N/A
MC74HC161ADR2	None	N/A
MC74HC161ADR2G	None	N/A
MC74HC161ADTR2	None	N/A
MC74HC161AFEL	None	N/A
MC74HC161AN	None	N/A
MC74HC161ANG	None	N/A
MC74HC163AD	None	N/A
MC74HC163ADG	None	N/A
MC74HC163ADR2	None	N/A
MC74HC163ADR2G	None	N/A
MC74HC163AFEL	None	N/A
MC74HC163AN	None	N/A
MC74HC163ANG	None	N/A
MC74HCT138ADG	None	N/A
MC74HCT138ADR2G	None	N/A
MC74HCT138ADTR2	None	N/A
MGB20N40CL	NGB15N41CL	ON Semiconductor
MGB20N40CLT4	NGB15N41CLT4	ON Semiconductor
MGP20N35CL	None	N/A
MGP20N40CL	NGP15N41CL	ON Semiconductor
MJC122WP	None	N/A
MJC15015WP	None	N/A
MJE13003	ST13003	ST Microelectronics
MJE13003G	KSE13003AA	Fairchild
MJEC44H11WP	None	N/A
MMDF4P03HDR2	NTMD3P03	ON Semiconductor
MMDJ3N03BJTR2	ZXT12N20DXTA	Zetex
MMDJ3P03BJTR2	ZXT12P20DXTA	Zetex
MMFT3055VT3G	NTF3055-100T3G	ON Semiconductor
MMT05B064T3	None	N/A
MTB2P50ET4	MTB2P50E	INDUSTRY
MTB30P06VG	MTB30P06VG	INDUSTRY
MTD20P03HDL1G	MTD20P03HDL1G	INDUSTRY

Issue Date: 31 Mar, 2005 Page 3 of 11



NTHS4111PT1G

NTMS4404NR2

Device to be Discontinued Recommended Replacement Supplier MTD20P03HDLG MTD20P03HDLG INDUSTRY MTD20P03HDLT4G MTD20P03HDLT4G INDUSTRY MTP30P06VG N/A None NCP1205DR2 None N/A NCP1230AD100R2 None N/A NCP1230AD133R2 None N/A NCP1230AD65R2 None N/A NCP1230AP100 None N/A NCP1230AP133 None N/A NCP1230AP65 None N/A NCP1442T None N/A NCP1443FR4 None N/A NCP1443T None N/A NCP1444T None N/A NCP1445FR4 None N/A NCP1445T N/A None NCP1573D None N/A NCP1573DR2 None N/A NCP3418D NCP3418ADR2 ON Semiconductor NCP3418DR2 ON Semiconductor NCP3418ADR2 NCP3418PD NCP3418ADR2 ON Semiconductor NCP3418PDR2 NCP3418ADR2 ON Semiconductor NCP5173MN None N/A NCP5173MNR2 None N/A NCS2203SN1T1 None N/A NCS2203SN1T1G None N/A NCS2203SN2T1 N/A None NCS2203SN2T1G None N/A NLSF302MNR2 N/A None NLSF302MNR2G N/A None NLSF308MNR2 None N/A NLSF308MNR2G None N/A NTB30N06 None N/A NTB75N06L N/A None NTB75N06LT4 None N/A NTD15N06 None N/A NTD15N06-001 None N/A NTD15N06-1G None N/A NTD15N06G None N/A NTD15N06L None N/A NTD15N06L-001 None N/A NTD15N06L-1G N/A None NTD15N06LG None N/A NTD15N06LT4 None N/A NTD15N06LT4G None N/A NTD15N06T4 None N/A NTD15N06T4G None N/A NTD30N02 None N/A NTD30N02T4 None N/A NTD30N02T4G None N/A NTHS4111PT1 None N/A

Issue Date: 31 Mar, 2005 Page 4 of 11

N/A

N/A

None

None



Product Discontinuance #13977

Device to be Discontinued	Recommended Replacement	Supplier
NTP30N06L	None	N/A
NTQD4154ZR2	None	N/A
NTQD4154ZR2G	None	N/A
SAC907LFBV	None	N/A
SBSG113MN	None	N/A
SCY99006R2	None	N/A
SCY99040DTBR2	None	N/A
SGP20N35CL	None	N/A
SJ81200	None	N/A
SJ8274	None	N/A
SJB42C	None	N/A
SJD1009T4	None	N/A
SJD1035T4	None	N/A
SJD1044T4	None	N/A
SJD117T4	None	N/A
SJD122T4	None	N/A
SJD44H11	None	N/A
SJD44H11-001	None	N/A
SJD44H11RL	None	N/A
SJD44H11T4	None	N/A
SJD47T4	None	N/A
SJE1397	None	N/A
SJE1763	None	N/A
SJE2167	None	N/A
SJE2776	None	N/A
SJE2894	None	N/A
SJE2985	None	N/A
SJE2985LFBU	None	N/A
SJE3001LFBV	None	N/A
SJE3014	None	N/A
SJE4021	None	N/A
SJE8030	None	N/A
SJEC13003WP	None	N/A
STB1081L3	NGB8206NT4	ON Semiconductor
STB1081L3T4	NGB8206NT4	ON Semiconductor
STB1081L3TF4	NGB8206NT4	ON Semiconductor
TE02221	None	N/A
TE02573T4	None	N/A
TEAC3055WP	None	N/A
TIPC127WP	None	N/A
VMC100E111FN	MC100E111FN	ON Semiconductor
VMC100E111FNG	MC100E111FNG	ON Semiconductor
VMC100E111FNR2	MC100E111FNR2	ON Semiconductor
VMC100E111FNR2G	MC100E111FNR2G	ON Semiconductor
VMC100EL16D	MC100EL16D	ON Semiconductor
VMC100EL16DR2	MC100EL16DR2	ON Semiconductor
VMC100EL16DR2G	MC100EL16DR2G	ON Semiconductor
VMC100LVE111FN	MC100LVE111FN	ON Semiconductor
VMC100LVE111FNG	MC100LVE111FNG	ON Semiconductor
VMC100LVE111FNR2	MC100LVE111FNR2	ON Semiconductor
VMC100LVE111FNRG VMC10E111FN	MC100LVE111FNR2G MC10E111FN	ON Semiconductor
		ON Semiconductor ON Semiconductor
VMC10E111FNG VMC10E111FNR2	MC10E111FNG MC10E111FNR2	ON Semiconductor
VMC10E111FNRZ VMC10EL16D	MC10E111FNR2 MC10EL16D	ON Semiconductor
AUCIOUTION	LICI OFFIT OD	on semiconductor

Issue Date: 31 Mar, 2005 Page 5 of 11



Device to be	Recommended	d Other						
Discontinued	Replacement	Recomme	ended	Replacem	nent	Commer	<u>nt</u>	
VMC10EL16DR2		EL16DR2		10	N Sem	icondu	ctor	
VMC10EL16DR2G	MC10E	EL16DR2G		ON	[Semi	iconduc	ctor	
MC78BC30NTR	None	Ricoh:	RN5RG	30AA-TR				
MC78BC31NTR	None	Ricoh:	RN5RG	31AA-TR				
MC78BC33NTR	None	Ricoh:	RN5RG	33AA-TR				
MC78BC33NTRG	None	Ricoh:	RN5RG	33AA-TR-	-FA			
MC78BC40NTR	None	Ricoh:	RN5RG	G40AA-TR				
MC78BC43NTR	None	Ricoh:	RN5RG	G43AA-TR				
MC78BC45NTR	None	Ricoh:	RN5RG	G45AA-TR				
MC78BC50NTR	None	Ricoh:	RN5RG	550AA-TR				
MC78FC28HT1	MC78FC28HT1G	None			Lead	d-free	Leadframe	
MC78FC30HT1	MC78FC30HT1G	None			Lead	d-free	Leadframe	
MC78FC33HT1	MC78FC33HT1G	None			Lead	d-free	Leadframe	
MC78FC40HT1	MC78FC40HT1G	None			Lead	d-free	Leadframe	
MC78FC50HT1	MC78FC50HT1G	None			Lead	d-free	Leadframe	
MC78PC18NTR	MC78PC18NTRG	None			Lead	d-free	Leadframe	
MC78PC25NTR	MC78PC25NTRG	None			Lead	d-free	Leadframe	
MC78PC28NTR	MC78PC28NTRG	None			Lead	d-free	Leadframe	
MC78PC30NTR	MC78PC30NTRG	None			Lead	d-free	Leadframe	
MC78PC33NTR	MC78PC33NTRG	None			Lead	d-free	Leadframe	
MC78PC50NTR	MC78PC50NTRG	None					Leadframe	
NCP802SAN1T1	NCP802SAN1T1G	None			Lead	d-free	Leadframe	
NCP802SAN5T1	NCP802SAN5T1G	None			Lead	d-free	Leadframe	
NCP802SAN6T1	NCP802SAN6T1G	None			Lead	d-free	Leadframe	
NCP802SN1T1	NCP802SN1T1G	None			Lead	d-free	Leadframe	
NCP4523G1T1	NCP4523G1T1G	None			Lead	d-free	Leadframe	
NCP4523G20T1	NCP4523G20T1G	None			Lead	d-free	Leadframe	
NCP4523G3T1	NCP4523G3T1G	None			Lead	d-free	Leadframe	

Issue Date: 31 Mar, 2005 Page 6 of 11



AFFECTED DEVICE LIST (WITHOUT SPECIALS)

1SS383T1G

2C3773WP

2N7008

2N7008RLRA

2N7008RLRE

BUL642D2

CS5212ED14

CS5212EDR14

CS5212GD14

CS5212GDR14

MBRM140ET1

MBRM140ET3

MBRM140ET3G

MC44608P100

MC74HC161AD

MC74HC161ADG

MC74HC161ADR2

MC74HC161ADR2G

MC74HC161ADTR2

MC74HC161AFEL

MC74HC161AN

MC74HC161ANG

MC74HC163AD

MC74HC163ADG

MC74HC163ADR2

MC74HC163ADR2G

MC74HC163AFEL

MC74HC163AN

MC74HC163ANG

MC74HCT138ADG

MC74HCT138ADR2G

MC74HCT138ADTR2

MC78BC30NTR

MC78BC31NTR

MC78BC33NTR

MC78BC40NTR

Issue Date: 31 Mar, 2005 Page 7 of 11



Product Discontinuance #13977

MC78BC43NTR

MC78BC45NTR

MC78BC50NTR

MC78FC30HT1

MC78FC33HT1

MC78FC40HT1

MC78FC50HT1

MC78PC18NTR

MC78PC25NTR

MC78PC28NTR

MC78PC30NTR

MC78PC33NTR

MC78PC50NTR

MGB20N40CL

MGB20N40CLT4

MGP20N35CL

MGP20N40CL

MJC122WP

MJC15015WP

MJE13003

MJE13003G

MJEC44H11WP

MMDF4P03HDR2

MMDJ3N03BJTR2

MMDJ3P03BJTR2

MMFT3055VT3G

MMT05B064T3

MTB2P50ET4

MTB30P06VG

MTD20P03HDL1G

MTD20P03HDLG

MTD20P03HDLT4G

MTP30P06VG

NCP1205DR2

NCP1230AD100R2

NCP1230AD133R2

NCP1230AD65R2

Issue Date: 31 Mar, 2005



Product Discontinuance #13977

NCP1230AP100

NCP1230AP133

NCP1230AP65

NCP1442T

NCP1443FR4

NCP1443T

NCP1444T

NCP1445FR4

NCP1445T

NCP1573D

NCP1573DR2

NCP3418D

NCP3418DR2

NCP3418PD

NCP3418PDR2

NCP4523G1T1

NCP4523G20T1

NCP4523G3T1

NCP5173MN

NCP5173MNR2

NCP802SAN1T1

NCP802SAN5T1

NCP802SAN6T1

NCP802SN1T1

NCS2203SN1T1

NCS2203SN1T1G

NCS2203SN2T1

NCS2203SN2T1G

NLSF302MNR2

NLSF302MNR2G

NLSF308MNR2

NLSF308MNR2G

NTB30N06

NTB75N06L

NTB75N06LT4

NTD15N06

NTD15N06-001

NTD15N06-1G

Issue Date: 31 Mar, 2005



Product Discontinuance #13977

NTD15N06G

NTD15N06L

NTD15N06L-001

NTD15N06L-1G

NTD15N06LG

NTD15N06LT4

NTD15N06LT4G

NTD15N06T4

NTD15N06T4G

NTD30N02

NTD30N02T4

NTD30N02T4G

NTHS4111PT1

NTHS4111PT1G

NTMS4404NR2

NTP30N06L

NTQD4154ZR2

NTQD4154ZR2G

SJB42C

SJD1044T4

SJD117T4

SJD44H11

SJD44H11-001

SJD44H11RL

SJD44H11T4

SJEC13003WP

STB1081L3

STB1081L3T4

TEAC3055WP

TIPC127WP

VMC100E111FN

VMC100E111FNG

VMC100E111FNR2

VMC100E111FNR2G

VMC100EL16D

VMC100EL16DR2

VMC100EL16DR2G

VMC100LVE111FN

Issue Date: 31 Mar, 2005



Product Discontinuance #13977

VMC100LVE111FNG

VMC100LVE111FNR2

VMC100LVE111FNRG

VMC10E111FN

VMC10E111FNG

VMC10E111FNR2

VMC10EL16D

VMC10EL16DR2

VMC10EL16DR2G

Issue Date: 31 Mar, 2005 Page 11 of 11