

### **Product Bulletin**

Document #: PB24207X2 Issue Date: 07 Oct 2022

Title of Change:	Update for PB24207X - To identify specific sites affected with the change including the transition period.				
Effective date:	07 Oct 2022				
Contact information:	Contact your local onsemi Sales Office or KrisJudelo.Dayna@onsemi.com				
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.				
Change Category:	Test Change				
Change Sub-Category(s):	Shipping/Packaging/Marking				
Sites Affected:					
onsemi Sites		External Foundry/Subcon Sites			
onsemi Cebu, Philippines		Greatek Electronics Inc., Taiwan			
onsemi Leshan, China		HANA Microelectronics, China			
onsemi Seremban, Malaysia		JCET, China			

### **Description and Purpose:**


This update to PB24207X is to list all of the affected sites and clarify that the transition period will be until Dec 31,2022.

SOSM and SOT223 package assembled in various listed sites will start to use onsemi Marking Layout Configuration

This is part of the alignment and marking standardization.

For a specific OPN that is build in different sites will now have the same lay out scheme and will just differ on the plant code.

Sample marking change below.



TEM001796 Rev. D Page 1 of 2

Marking.

Some products may not follow the Generic



## **Product Bulletin**

Document #: PB24207X2 Issue Date: 07 Oct 2022

### **List of Affected Standard Parts:**

**Note**: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

FDC6301N	FDC6303N	FDC6305N	
FDC6306P	FDC6310P	FDC6312P	
FDC6318P	FDC6321C	FDC6323L	
FDC6324L	FDC6325L	FDC6326L	
FDC6327C	FDC6329L	FDC658AP	
FDC6561AN	FDC655BN-G	FDC654P	
FDC653N	FDC645N	FDC6420C	
FDC640P	FDC6401N	FDC638P-P	
FDC638P	FDC638APZ-SBMS001	FDC638APZ-PSBMS001	
FDC637AN	FDC634P	FDC6333C-G	
FDC6333C	FDC6331L	FDC6330L	
FDC610PZ-G	FDC606P	FDC604P	
FDC602P	FDC5661N-F085	FDC5614P	
FDC5612	FDC3612	FDC3601N	
FDC3512	FDC30N20DZ	FDC2612	
FDC2512-P	FDC2512	FDC013P20L	

TEM001796 Rev. D Page 2 of 2



# **Appendix A: Changed Products**

PCN#: PB24207X2 Issue Date: Oct 07, 2022

DIKG: DIGI-KEY

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier		
FDC6301N						
FDC6305N						
FDC6306P						
FDC6310P						
FDC6312P						
FDC6318P						
FDC6321C						
FDC6323L						
FDC6324L						
FDC6325L						
FDC6326L						
FDC6327C						
FDC6329L						
FDC658AP						
FDC6561AN						
FDC654P						
FDC653N						
FDC645N						
FDC6420C						
FDC640P						
FDC6401N						
FDC638P						
FDC637AN						
FDC634P						
FDC6333C						
FDC6331L						
FDC6330L						
FDC606P						
FDC604P						
FDC602P						
FDC5661N-F085						
FDC5614P						
FDC5612						
FDC3612						
FDC3601N						
FDC3512						
FDC30N20DZ						
FDC2612						
FDC2512						
FDC6303N						