

| Title of Change: | 3Q2022 Product Discontinuance Notice - Batch 5 (Standard) | | |
|-----------------------|---|--|--|
| Last Time Buy Date: | 30 Mar 2023 | | |
| Last Ship Date: | 30 Sep 2023 | | |
| Contact information: | Contact your local onsemi Sales Office or PCN.Support@onsemi.com | | |
| Type of notification: | Customers must notify onsemi (< <u>PCN.Support@onsemi.com</u> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life. | | |

Description and Purpose:

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, onsemi is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. onsemi continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

onsemi wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas: Tom Siegel (tom.siegel@onsemi.com) 2 +1 765 868 5022 USA Europe: Andrej Tomasik (andrej.tomasik@onsemi.com) ☎ +421 33790 2229 Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com) ☎ +81 3 6880 1771 Japan Asia Pacific: Stephen Ng (stephen.ng@onsemi.com) ☎+852 2689 0209 China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, onsemi ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

| Device to be Discontinued | Replacement part | Supplier |
|---------------------------|------------------------|----------|
| 2SD1816T-TL-E | MJD243 | onsemi |
| NTZD3154NT5G | NTZD3154NT1G | onsemi |
| FDPC8014S | #NONE | #NA |
| FDMC035N10X1 | #NONE | #NA |
| FDMS8020 | #NONE | #NA |
| FDMS7658AS | #NONE | #NA |
| STTFS010N10MCL | STTFS015N10MCL | onsemi |
| FDFS2P106A | FDC5614P | onsemi |
| MC34167TVG | MC33167TVG | onsemi |
| MBRB2535CTLT4G | MBRB2545CTT4G | onsemi |
| RHRP3060 | #NONE | #NA |
| RHRG5060 | #NONE | #NA |
| ISL9R3060G2 | #NONE | #NA |
| HGTG20N60B3D | #NONE | #NA |
| FSA3357K8X | #NONE | #NA |
| MBRB60H100CTT4G | NRVBB60H100CTT4G | onsemi |
| NB3N853501EDTG | NB3N853501EDTR2G | onsemi |
| CAT25128VI-G | CAT25128VI-GT3 | onsemi |
| NCP705EMT33TCG | NCP705MT33TCG | onsemi |
| FDMC8878 | FDMC8882 | onsemi |
| MURB1660CTT4G | NRVUB1660CTT4G | onsemi |
| AR0135CS2C00SUEA0-DPBR1 | AR0135CS2C00SUEA0-DPBR | onsemi |
| SBX201C-TB-E | NSR201MXT5G | onsemi |
| SBX201C-L-TB-E | NSR201MXT5G | onsemi |
| CPH5506-TL-E | CPH5520-TL-E | onsemi |
| NTD5802NT4G | #NONE | #NA |
| RHRG30120 | #NONE | #NA |
| HGTG30N60A4D | #NONE | #NA |
| FFA60UP20DNTU | #NONE | #NA |
| 2SA2012-TD-E | 2SA2016-TD-E | onsemi |
| FAN301ULMY | #NONE | #NA |
| FAN301HLMY-FV16 | #NONE | #NA |
| FAN301HLMY-FS16 | #NONE | #NA |

Appendix A: Changed Products

PCN#: PD24971XB Issue Date: Sep 30, 2022

DIKG: DIGI-KEY

| Product | Customer Part Number | Qualification Vehicle | New Part Number | Replacement Supplier |
|-------------------------|----------------------|-----------------------|------------------------|----------------------|
| 2SD1816T-TL-E | | | MJD243 | onsemi |
| FDPC8014S | | | #NONE | #NA |
| FDMS8020 | | | #NONE | #NA |
| FDMS7658AS | | | #NONE | #NA |
| STTFS010N10MCL | | | STTFS015N10MCL | onsemi |
| FDFS2P106A | | | FDC5614P | onsemi |
| MC34167TVG | | | MC33167TVG | onsemi |
| MBRB2535CTLT4G | | | MBRB2545CTT4G | onsemi |
| RHRP3060 | | | #NONE | #NA |
| RHRG5060 | | | #NONE | #NA |
| ISL9R3060G2 | | | #NONE | #NA |
| HGTG20N60B3D | | | #NONE | #NA |
| FSA3357K8X | | | #NONE | #NA |
| MBRB60H100CTT4G | | | NRVBB60H100CTT4G | onsemi |
| CAT25128VI-G | | | CAT25128VI-GT3 | onsemi |
| NCP705EMT33TCG | | | NCP705MT33TCG | onsemi |
| FDMC8878 | | | FDMC8882 | onsemi |
| MURB1660CTT4G | | | NRVUB1660CTT4G | onsemi |
| AR0135CS2C00SUEA0-DPBR1 | | | AR0135CS2C00SUEA0-DPBR | onsemi |
| SBX201C-TB-E | | | NSR201MXT5G | onsemi |
| SBX201C-L-TB-E | | | NSR201MXT5G | onsemi |
| CPH5506-TL-E | | | CPH5520-TL-E | onsemi |
| NTD5802NT4G | | | #NONE | #NA |
| RHRG30120 | | | #NONE | #NA |
| HGTG30N60A4D | | | #NONE | #NA |
| FFA60UP20DNTU | | | #NONE | #NA |
| 2SA2012-TD-E | | | 2SA2016-TD-E | onsemi |
| NTZD3154NT5G | | | NTZD3154NT1G | onsemi |